

HT812 Firmware Release Note

IMPORTANT UPGRADING NOTE

• For HT812, once upgraded to 1.0.2.5 or above, downgrading to 1.0.1.x firmware version or lower is not supported.



Table of Content

IMPORTANT UPGRADING NOTE	1
FIRMWARE VERSION 1.0.2.5	3
PRODUCT NAME	3
DATE	3
IMPORTANT UPGRADING NOTE	3
ENHANCEMENT	3
BUG FIX	3
NEW FEATURES OVERVIEW	4
OPUS Payload Type Default Value	4
PORTANT UPGRADING NOTE 1 MWARE VERSION 1.0.2.5 3 PRODUCT NAME 3 DATE 3 IMPORTANT UPGRADING NOTE 3 ENHANCEMENT 3 BUG FIX 3 NEW FEATURES OVERVIEW 4 OPUS Payload Type Default Value 4 MWARE VERSION 1.0.2.3 5 PRODUCT NAME 5 DATE 5 IMPORTANT UPGRADING NOTE 5 ENHANCEMENT 5 BUG FIX 5 NEW FEATURES OVERVIEW 6 WAN PORT WEB ACCESS 6 PASSWORD CHANGE CONFIRMATION 7	
PRODUCT NAME	5
IMPORTANT UPGRADING NOTE	5
ENHANCEMENT	5
BUG FIX	5
NEW FEATURES OVERVIEW	6
PASSWORD CHANGE CONFIRMATION	



FIRMWARE VERSION 1.0.2.5

PRODUCT NAME

HT812

DATE

11/01/2016

IMPORTANT UPGRADING NOTE

 For HT812, once upgraded to 1.0.2.3 or above, downgrading to 1.0.1.x firmware version or lower is not supported.

ENHANCEMENT

• Changed OPUS Payload Type default value to 123 to match other GS products.

BUG FIX

- Fixed The value of DTMF payload can be set to empty.
- Fixed HT812 would crash after failed attended transfer as transferee.
- Fixed HT812 does not play ring back tone in Broadsoft mode if Call-Waiting Caller ID is Disabled.
- Fixed No CID with callback from call on hold.
- Fixed DUT will play ring back tone after playing call waiting tone.
- Fixed Call audio would become very poor If change RTP mode to SRTP after call transferred.
- Fixed Device did not prompt "Device not registered" when use Spanish IVR.
- Fixed DUT cannot open configure file that download through TR-069.




NEW FEATURES OVERVIEW

This section lists major new features and describes how to use it from the user's point of view.

OPUS Payload Type Default Value

• Web Configuration

User can find the re-enter confirm box at Web -> Profile Settings



Functionality

Change OPUS Payload Type default value to 123.



FIRMWARE VERSION 1.0.2.3

PRODUCT NAME

HT812

DATE

10/05/2016

IMPORTANT UPGRADING NOTE

• For HT812, once upgraded to 1.0.2.3 or above, downgrading to 1.0.1.x firmware version or lower is not supported.

ENHANCEMENT

- Added network check mechanism to enable or disable WAN port web access. [WAN PORT WEB ACCESS]
- Added a re-enter box to confirm change user and admin password on web GUI to avoid typo or mistakes. [PASSWORD CHANGE CONFIRMATION]

BUG FIX

- Fixed HT812 cannot off-hook normally when register server is domain and sip transport is TLS
- Fixed call waiting tone only play once.
- Fixed HT812 used an incorrect User-Agent when sending configure file request to UCM.
- Fixed HT812 will play ring back tone after playing call waiting tone.
- Fixed If the value of On Hook Timing set to less than 80ms, the FXS port cannot detect on hook event.
- Fixed After changed sip port, only account 1 will take effect and all other accounts will use random port instead.
- Fixed When setting the language to "Spanish IVR", some options on web page will display Spanish.
- Changed default Call Waiting Tone to f1=440@-13,c=300/10000;



NEW FEATURES OVERVIEW

This section lists major new features and describes how to use it from the user's point of view.

WAN PORT WEB ACCESS

• Web Configuration

These settings can be found at Web -> Basic Settings -> WAN side HTTP/Telnet access:

NAT/DHCP Server Information & Configuration:				
	Device Mode:	NAT Router		
	NAT maximum ports:	1024 (range: 0 - 4096, default is 1024)		
	NAT TCP timeout:	3600 (range: 0 - 3600, default is 3600)		
	NAT UDP timeout:	300 (range: 0 - 3600, default is 300)		
	Uplink bandwidth:	Disabled ▼		
	Downlink bandwidth:	Disabled ▼		
	Enable UPnP support:	No		
	Reply to ICMP on WAN port:	No		
	WAN side HTTP/Telnet access: No Pes Auto (WAN side access allowed for private IP; rejected for public IP) Cloned WAN MAC Addr: (in hex format)			
l I				
	Enable LAN DHCP:	○ No ● Yes		
	LAN DHCP Base IP:	192.168.2.1 (base IP for the LAN port, default is 192.168.2.1)		
	LAN DHCP Start IP:	192.168.2.100 (default is 192.168.2.100)		
	LAN DHCP End IP:	192.168.2.199 (default is 192.168.2.199)		
	LAN Subnet Mask:	255.255.255.0 (default is 255.255.255.0)		
	DHCP IP Lease Time:	(in units of hours, default is 120 hours or 5 days)		
	DMZ IP:			

Functionality

Added an option of "Auto" for WAN side HTTP/Telnet access, and set this option as default value. If the device is using public IP, the WAN Port web access will be disabled by default.

If the device is using private IP, the WAN Port web access will be enabled by default.

New P Values

Pvalue	Description	Value range	Default
P190	WAN side HTTP/Telnet access	0 – No	2 - Auto
		1 – Yes	
		2 – Auto (New added)	



PASSWORD CHANGE CONFIRMATION

• Web Configuration

User can find the re-enter confirm box at Web ->Basic Settings/Advanced Settings

Grandstream Device Configuration					
STATUS RASIC SETTINGS ADVANCED SETTINGS PROFILE 1 PROFILE 2 FXS PORTS					
2.0	End User Password: End User Password: Web Port: 80	(purposely not displayed for security protection) (default for HTTP is 80)			
Grandstream Device Configuration					
	STATUS BASIC SET	INCS ADVANCED SETTINGS PROFILE 1 PROFILE 2 FXS PORTS			
	New Admin Passwo Confirm Admin Passwo				

Functionality

Allow user to re-enter the password to confirm the password is input correctly.