

HT801/802/812/814/818 Firmware Release Notes

IMPORTANT UPGRADING NOTE

The previous release notes can be downloaded here:

HT801/802: https://firmware.grandstream.com/Release_Note_HT80x_1.0.35.4.pdf

HT812/814: https://firmware.grandstream.com/Release_Note_HT812_HT814_1.0.35.4.pdf

HT818: https://firmware.grandstream.com/Release Note HT818 1.0.35.4.pdf

- Once HT801/HT802/HT812/HT814 is upgraded to 1.0.43.11 or above, downgrading to 1.0.41.2 or lower firmware version is not supported because of support for 2nd generation individual certificate.
- Once HT818 is upgraded to 1.0.43.10 or above, downgrading to 1.0.41.2 or lower firmware version is not supported because of support for 2nd generation individual certificate.
- If HT8xx firmware version is equal or older than in 1.0.39.4, users cannot use web UI option "Upload from Local Directory" to upload a firmware file equal to or newer than 1.0.41.2. Please configure web UI option "Firmware Upgrade and Provisioning" to set a valid method for the device to obtain firmware via TFTP/HTTP/HTTPS over the network. Please see section "Upgrading and Provisioning" in https://dx.doi.org/10.108/j.com/HT80X-Administration-Guide, and HT818 Administration Guide for details.
- Once HT801/HT802/HT812/HT814 is upgraded to 1.0.41.2 or above, downgrading to 1.0.39.4 or lower firmware version is not supported on below HW:

HT801: 6.0A HT802: 2.7A HT812: 6.0A HT814: 5.0A

- If HT801/802 firmware version is older than 1.0.33.4, users cannot use web UI option "Upload from Local Directory" to upload a firmware file equal to or newer than 1.0.33.4. Please configure web UI option "Firmware Upgrade and Provisioning" to set a valid method for the device to obtain firmware via TFTP/HTTP/HTTPS over the network. Please see section "Upgrading and Provisioning" in HT80X Administration Guide for details.
- Once HT801 HW 4.0A is upgraded to 1.0.29.8 or above, downgrading to lower firmware version is not supported.



• Once HT801/HT802 is upgraded to 1.0.27.2 or above, downgrading to lower firmware version is not supported on below HW:

HT801: 3.1A HT802: 2.0A

• Once HT801/HT802 is upgraded to 1.0.23.5 or above, downgrading to lower firmware version is not supported on below HW:

HT801: 1.1B, 1.1C, HT802: 1.6B, 1.6C

- Once HT801/HT802 is upgraded to 1.0.3.2 or above, downgrading to 1.0.2.x firmware version or lower is not supported.
- Once HT801/HT802 is upgraded to 1.0.2.7, downgrading to 1.0.1.x firmware version or lower is not supported.
- Once HT812/HT814 is upgraded to 1.0.35.4 or above, downgrading to a lower firmware version is not supported on the below HW:

HT812: 4.0A HT814: 3.0A

• Once HT812/HT814 is upgraded to 1.0.31.1 or above, downgrading to a lower firmware version is not supported on the below HW:

HT812: 3.0A HT814: 2.0A

• Once HT812/HT814 is upgraded to 1.0.23.5 or above, downgrading to a lower firmware version is not supported on the below HW:

HT812: 1.6A, 1.6C, 1.6D HT814: 1.7D, 1.7E, 1.7C

- Once HT812/HT814 is upgraded to 1.0.3.2 or above, downgrading to 1.0.2.x firmware version or lower is not supported.
- Once HT812/HT814 is upgraded to 1.0.2.x, downgrading to 1.0.1.x firmware version or lower is not supported.
- Once HT818 is upgraded to 1.0.31.1 or above, downgrading to a lower firmware version is not supported on HW 1.6A.



Table of Content

IMPORTANT UPGRADING NOTE	1
FIRMWARE VERSION 1.0.45.2	6
PRODUCT NAME	6
DATE	
FIRMWARE FILE INFORMATION	
ENHANCEMENT	6
BUG FIX	6
NEW FEATURES OVERVIEW	7
Download and Process All Available Config Files	7
When To Restart Session After Re-INVITE received	
FIRMWARE VERSION 1.0.43.11	9
PRODUCT NAME	9
DATE	9
FIRMWARE FILE INFORMATION	9
ENHANCEMENT	9
BUG FIX	10
NEW FEATURES OVERVIEW	11
Enable TR069 Through Management Interface	11
Enable Syslog Through Management Interface	12
Enable using tags in the URL	12
With Secret Key Information	13
Security Controls for SSH/Telnet Access	13
Additional Override DHCP Option	14
From Domain	
SRTP Key Length	
Inband DTMF Duration	
DSP DTMF Detector Duration Threshold	16
FIRMWARE VERSION 1.0.43.10	17
PRODUCT NAME	
DATE	
FIRMWARE FILE INFORMATION	
ENHANCEMENT	
BUG FIX	18
NEW FEATURES OVERVIEW	20



Enable TR069 Through Management Interface	20
Enable Syslog Through Management Interface	20
Enable using tags in the URL	21
With Secret Key Information	21
Security Controls for SSH/Telnet Access	22
Additional Override DHCP Option	23
From Domain	23
SRTP Key Length	24
Inband DTMF Duration	24
DSP DTMF Detector Duration Threshold	25
FIRMWARE VERSION 1.0.41.5	26
PRODUCT NAME	26
DATE	26
FIRMWARE FILE INFORMATION	26
BUG FIX	26
FIRMWARE VERSION 1.0.41.2	27
PRODUCT NAME	27
DATE	27
FIRMWARE FILE INFORMATION	27
ENHANCEMENT	27
BUG FIX	27
FIRMWARE VERSION 1.0.39.4	28
PRODUCT NAME	28
DATE	28
FIRMWARE FILE INFORMATION	28
ENHANCEMENT	28
BUG FIX	28
NEW FEATURES OVERVIEW	29
Enable SNMP Through Management Interface	29
Subscribe Retry Wait Time upon 403 Forbidden	29
E911/HELD Protocol	30
FIRMWARE VERSION 1.0.37.1	34
PRODUCT NAME	34
DATE	34
FIRMWARE FILE INFORMATION	34
ENHANCEMENT	34
BUG FIX	34



KNOWN ISSUES	34
NEW FEATURES OVERVIEW	34
Configuration File Types Allowed	35
MAC in User-Agent	
Use MAC Header	36



FIRMWARE VERSION 1.0.45.2

PRODUCT NAME

HT801, HT802, HT812, HT814, HT818

DATE

02/15/2023

FIRMWARE FILE INFORMATION

HT801 firmware file name: ht801fw.bin
 MD5: 4f323e920c46d04cb23e6e73f30aad15

• HT802 firmware file name: ht802fw.bin

MD5: 7b50751cd4286b288699231d24394d9f

• HT812 firmware file name: ht81xfw.bin

MD5: f6b5c16bd8f2ce8919dea22fb2906a9a

• HT814 firmware file name: ht81xfw.bin

MD5: f6b5c16bd8f2ce8919dea22fb2906a9a

• HT818 firmware file name: ht818fw.bin

MD5: 16b86e29c1b4858cda24f9e688a5fae0

ENHANCEMENT

- Added override config file option "cfgMAC_override.xml".
- Added option "Download and Process All Available Config File. [Download and Process All Available Config Files]
- Added option "When To Restart Session After Re-INVITE received" [When To Restart Session After Re-INVITE received]
- Updated the option in "Unregister On Reboot" to 0 No, 1 All, 2 Instance.

- Fixed device Call quality data not reported after the device factory reset.
- Fixed device Enabling Flash Digit Control should disable transfer using the flash key.
- Fixed the voice prompt *98 conflict issue with UCM.
- Fixed the DNS SRV Using the registered IP address function does not take effect.
- Fixed a bug that causes the device not start sending RTP.
- Fixed the sip server address and port settings that do not conform to the rules can be saved.
- Fixed CPE doesn't recover XMPP session when XMPP server goes down.
- Fixed an issue that notification has not been sent to the ACS.
- [HT8xx] Fixed device DDNS Username and DDNS Password could not save as null.
- [HT8xx] Fixed device issue causes stops registering.



- [HT8xx] Fixed device After the fax is sent, no audio on either side and the IVR becomes invalid.
- [HT818] Fixed the SSH cannot log in after factory restoration.
- Fixed when using the Russian page, there is an incomplete translation of a setting item.
- Fixed inbound long-duration call fails under certain configuration.
- Fixed an issue that causes by No audio for the second call received.
- Fixed the Syslog enabled on the HT device in the local deployment, and the content of the syslog package is empty.
- Fixed an error make a wrong or missing prompt for IVR diagnostics.
- Fixed the authenticate server certificate domain or chain option needs to be restarted to take
 effect.
- Fixed the software stops when using "Replace Beginning '+' with 00 in Caller ID" feature.
- Fixed the DTMF Negotiation Fails Upon Transfer.
- Fixed the firmware upgrade by TR069 doesn't use Target Filename.
- Fixed the configuration file that was downloaded from WebUI cannot be used.
- Fixed device as transferee cannot back to call if the transfer failed.
- Fixed device stops sending periodic information after a time.
- [HT8xx] Fixed the device software process stops after the group is started.
- [HT818] Fixed device when the failover SIP server address is domain name plus port registration, and the sending destination port is wrong.
- [HT818] Fixed after modifying the firmware server IP address or configuration server IP address via IVR, there is a probability that the wrong IP address will be broadcast.


NEW FEATURES OVERVIEW

This section lists major new features and describes how to use them from the user's point of view.

Download and Process All Available Config Files

Web Configuration

Users can find the configuration section in Web -> Advanced Settings.



Functionality

This feature allows users to download and process all available config files. By default, the device will provision the first available config in the order of cfgMAC, cfgMAC.xml, cfgMODEL.xml, and cfg.xml (corresponding to device-specific, model specific, and global configs). If this option is enabled, the phone



will inverse the downloading process to cfg.xml > cfgMODEL.xml > cfgMAC.bin > cfgMAC.xml. The following files will override the files that have already been loaded and processed.

Pvalue	Description	Value Range	Default
8467	Download and Process All	0 - No	0 - No
	Available Config Files	1 - Yes	

When To Restart Session After Re-INVITE received

Web Configuration

Users can find the configuration section in Web -> Profile 1 or 2

Force INVITE:	No	27
TO/CE HVVIII.	10 C Tes (Always Tellesii Willi IIVVII E Ilistea	id of OFDATE)
When To Restart Session After Re-INVITE received:	● Immediately ○ After replying 2000K	
Enable 100rel:	● No ○ Yes	

Functionality

This feature allows users to support delays posting MediaChange Event.

Pvalue	Description	Value Range	Default
28744	When To Restart Session After	0 - Immediately	0 - Immediately
	Re-INVITE received (FXS1 or	1 - After replying 2000K	
	Profile1)		
28745	When To Restart Session After	0 - Immediately	0 - Immediately
	Re-INVITE received (FXS2 or	1 - After replying 200OK	
	Profile2)		



FIRMWARE VERSION 1.0.43.11

PRODUCT NAME

HT801, HT802, HT812, HT814

DATE

12/1/2022

FIRMWARE FILE INFORMATION

HT801 firmware file name: ht801fw.bin
 MD5: 22ebe2d275303e29a1db50b5b50fbb67

HT802 firmware file name: ht802fw.bin
 MD5: 05681126b5bfc789f507db2e108e0f62

HT812 firmware file name: ht812fw.bin
 MD5: 3beec47975dc18ad062380b352baf726

HT814 firmware file name: ht814fw.bin
 MD5: 3beec47975dc18ad062380b352baf726

ENHANCEMENT

- Added Charter CA to the approved certificate list.
- Added support for TR-069 on the management interface. [Enable TR069 Through Management Interface]
- Added ability to send Syslog traffic through Management Interface.[Enable Syslog Through Management Interface]
- Added support for variable on Provisioning link. [Enable using tags in the URL]
- Updated the default option of "Disable Reminder Ring for DND (P29072/29172)" to "1 - Yes".
- Optimized Syslog makes it more user-friendly.
- Add SSL Key Log File. [With Secret Key Information]
- Allow configuring devices through SSH from different networks. [Security Controls for SSH/Telnet Access]
- Added additional Flash Digit events.
- Optimized the layout of the software version on the status page to make it looks better.
- Add support of DHCP Option 150. [Additional Override DHCP Option]
- Add new special feature option "138- GIBTELECOM" (Profile1 or 2-> Special Feature-> GIBTELECOM).
- Add support for the "From Domain" option. [From Domain]
- GUI enhancement to display correctly port status.
- Added support for SRTP Key Length. [SRTP Key Length]
- Added HT81x support for Inband DTMF Duration. [Inband DTMF Duration]



- Added HT81x support for DSP DTMF Detector Duration Threshold. [DSP DTMF Detector Duration Threshold]
- Added support following up not on WebUI pvalues:
 - P61701/61702 TR-069 firewall rules (Value Range:1-65535, no default)
 - P8603 Root CA Version (0 Current Root; 1 New Root, default is 1)
 - P8604 Provision and upgrade to new Gen-2 certificate. (1- upgrade; 0 no upgrade, default is 0).
 - P8605 Contents (text string) of Gen-2 certificate to upgrade. (String. Maxlength 8192, no default)
 - P8606 Contents (text string) of Gen-2 EC private key to upgrade. (String. Maxlength 8192, no default)
 - P8615 Disable filename in URL for config provision. (1 -Yes, 0 No, default is 0)
 - P8616 Disable filename in URL for firmware upgrade. (1 -Yes, 0 No, default is 0)

- Fixed device faxes may not be sent and received normally with specific fax machines.
- Fixed device still uses a random port for SIP registration when it's set to "No" on BroadSoft.
- Fixed device plays priority alert call waiting tone incorrectly on BroadSoft.
- Fixed device plays Alternate Number Call Waiting Tone incorrectly on BroadSoft.
- Fixed device cannot enable local call feature using certain dial plan on BroadSoft.
- Fixed a bug that causes server input not to conform to the rule.
- Fixed a bug that causes an ATA crash after calling itself.
- Fixed incorrect network information in SSH.
- Fixed retry wait time when subscribing to 403 Forbidden is always displayed in English when the language is switched.
- Fixed device cannot access the page and establish a call after unplugging and plugging the network cable while on PPPoE and OpenVPN network.
- Fixed device cannot config "OpenVPN Transport" via TR069.
- Fixed device didn't send HTTP to ACS if only IPV6 in WIFI.
- Fixed device OUI reported by CPE mismatch with real OUI in MAC address.
- Fixed an issue that causes the device still ring on DND.
- Fixed the log server domain name resolution order is incorrect.
- Fixed the bug that causes the device will not send require when the path contains "%".
- Fixed the HT81x bug that causes the devices to resend the OpenVPN request process every five seconds after unplugging the network cable.
- Fixed device deleting node via ACS server will cause CPE crash.
- Fixed an error that causes a CPE crash while executing DeleteObject.
- Fixed device Audio lost when call waiting for caller ID is enabled.
- Fixed the checked state error when the Priority Header parameter is set to "Yes".
- Fixed the bug caused by Call waiting dropped by MTAS Server.
- Fixed the status light is abnormal after the FTP upgrade fails.
- Fixed the copyright not translated into the Russian language on the Russian page.
- Fixed the bug that causes the call cannot to be resumed after pressing hold.



- Fixed device local RBT not played after 180 ringing.
- Fixed device the forced SRTP * 18 function is not effective when it is currently effective.
- Fixed device memory is OOM when the 1.0.41.2 version is changed.
- Fixed device high pitch beep present with first call waiting tone.
- Fixed a call forward fails issue on Zoom.
- Fixed HT8xx devices call gets ended by the server after 30 mins on hold on Zoom.
- Fixed HT81x devices sends out REGISTER to 4 accounts after provisioned with 4 FXS ports info on Zoom.
- Fixed device when calling certain numbers, the user will get a long ringback tone.
- Fixed device Jitter Buffer Type not getting used.
- Fixed device after the local three-party conference ends, the phone reports the call status as P2P.
- Fixed device after filling in the Custom Certificate with the GEN 1 certificate, sips TLS registration failed.
- Fixed device RTPevent flash is not sent before a call is established.
- Fixed device If the device IP and gateway are not in the same network segment, no error will be prompted.
- Fixed HT81x devices that can't dial and are unable to access the web during running the "FAX" case.
- Fixed HT81x devices after the fax is sent, no audio on both sides, and the IVR becomes invalid.

NEW FEATURES OVERVIEW

This section lists major new features and describes how to use them from the user's point of view.

Enable TR069 Through Management Interface

Web Configuration

Users can find the configuration section in Web -> Basic Settings.

Enable SNMP Through Management Interface:	No	O Yes	
Enable TR069 Through Management Interface:	No	○ Yes	
Enable Syslog Through Management Interface:	No	O Yes	

Functionality

This feature allows users to route TR069 packets through the management interface.

Ī	Pvalue	Description	Value Range	Default



8607	Enable TR069 Through	0 - No	0 - No
	Management Interface	1 - Yes	

Enable Syslog Through Management Interface

• Web Configuration

Users can find the configuration section in Web -> Basic Settings.

Enable TR069 Through Management Interface:	No	O Yes	
Enable Syslog Through Management Interface:	No	O Yes	
Management Interface IPv4 Address:		LAN Tag 0 iority value 0	(0-4094)

Functionality

This feature allows users to route Syslog packets through the management interface.

Pvalue	Description	Value range	Default
8610	Enable Syslog Through	0 - No	0 - No
	Management Interface	1 - Yes	

Enable using tags in the URL

• Web Configuration

Users can find the configuration section in Web -> Advanced Settings.

Firmware File Prefix: Config File Prefix:	Firmv Config
Enable using tags in URL: No Yes	
Always send HTTP Basic Authentica	tion Informatio



Functionality

This feature allows users can configure variables on the configuration server path to differentiate the directories on the server.

Pvalue	Description	Value range	Default
8609 Enable using tags in the URL		0 - No	0 - No
		1 - Yes	

With Secret Key Information

Web Configuration

Users can find the configuration section in Web -> Advanced Settings.-> Information Capture-> Capture

Syslog Level: Send SIP Log:	DEBUG ✓ No ○ Yes
Information Capture:	Capture
	NoYes, reboot every day at hour1 (0-23)
Automatic Reboot:	1 (0-23)

Grandstream Device Configuration								
<u>STATUS</u>	BASI	C SETTINGS	ADVANCED SET	TINGS	PROFILE 1	PROFILE 2	FXS PORTS	
		With Secret	Key Information:	O No	Yes			
			Status:	Idle				
			Capture File:	None				
			Start	Stop				

Functionality

This feature allows users to make packet capture including the secret key to decrypt the captured TLS packets.


Pvalue	Description	Value range	Default
22419 With Secret Key Information		0 - No	0 - No
		1 - Yes	

Security Controls for SSH/Telnet Access

• Web Configuration

Users can find the configuration section in Web -> Basic Settings.





Functionality


This feature allows users to Security Control the Pvalue for SSH or Telnet Access:

Pvalue	Description	Value range	Default
28210	Security Controls for SSH/Telnet	0 - Only allow SSH	3 - Allow any user
	Access	private IP users to set	to set any Pvalue
		system Pvalue	
		1 - Allow all SSH users	
		to set system Pvalue	
		2 - Allow all SSH users	
		to set any Pvalue	
		3 - Allow any user to set	
		any Pvalue	
		4 - Prohibit setting	
		Pvalue	

Additional Override DHCP Option

Web Configuration

Users can find the configuration section in Web -> Advanced Settings.



Functionality

This feature allows users to enable the Additional Override DHCP Option in Option 150.



Pvalue	Description	Value range	Default
8337	Additional Override DHCP	0 – None	0 – None
	Option	1 – Option 150	

From Domain

• Web Configuration

Users can find the configuration section in Web -> Profile 1 or 2

Prefer Primary Outbound	O No	O Yes	(yes - will reregister via Primary Outbound Proxy if registration expires)
From Domain:	9		(Optional, actual domain name, will override the from header)
Allow DHCP Option 120 (override SIP server):	No	O Yes	
100000000000000000000000000000000000000			

Functionality

This feature allows users to add the actual domain name, it will override the from header.

Pvalue	Description	Value range	Default
8617	From Domain	String	Null
8618			

SRTP Key Length

• Web Configuration

Users can find the configuration section in Web -> Profile 1 or 2

Jitter Buffer Length:	■ Low O Medium O High
SRTP Mode:	Oisabled ○ Enabled but not forced ○ Enabled and forced
SRTP Key Length:	AES 128&256 bit ✓
Crypto Life Time:	O Disabled Enabled

Functionality

This feature allows users to select supported SRTP Key Length.

Pvalue	Description	Value range	Default
2383	SRTP Key Length	0 - AES 128&256 bit	0 - AES 128&256
2483		1 - AES 128 bit	bit
		2 - AES 256 bit	



Inband DTMF Duration

Web Configuration

Users can find the configuration section in Web -> Profile 1 or 2

	Priority 2: SIP INFO ✓ Priority 3: In-audio ✓
Inband DTMF Duration:	In 40-2000 milliseconds range, duration: 100 inter-duration: 50
DSP DTMF Detector Duration Threshold:	

Functionality

This feature allows users to config the Inband DTMF Duration.

Pvalue	Description	Value range	Default
28134	Inband DTMF Duration - duration	Min: 40	100
28135		Max: 2000	
28138	Inband DTMF Duration -	Min: 40	50
28139	inter-duration	Max: 2000	

DSP DTMF Detector Duration Threshold

• Web Configuration

Users can find the configuration section in Web -> Profile 1 or 2

		•			
In	band DTMF Duration:	In 40-2000 milliseconds range, duration:	100	inter-duration:	50
	DSP DTMF Detector Duration Threshold:	In 20-200 milliseconds range, duration:	30	inter-duration:	30
Disal	ole DTMF Negotiation:	O No (negotiate with peer) • Yes (use	above DTN	IF order without ne	gotiation)

Functionality

This feature allows users to config the DSP DTMF Detector Duration Threshold.

Pvalue	Description	Value range	Default
28201	DSP DTMF Detector Duration	Min: 20	30
28202	Threshold - duration	Max: 200	
28205	DSP DTMF Detector Duration	Min: 20	30
28206	Threshold - inter-duration	Max: 200	



FIRMWARE VERSION 1.0.43.10

PRODUCT NAME

HT818

DATE

11/30/2022

FIRMWARE FILE INFORMATION

HT818 firmware file name: ht818fw.bin
 MD5: 0d6ae6e257c759325d11fa0a2b108da2

ENHANCEMENT

- Added Charter CA to the approved certificate list.
- Added support for TR-069 on the management interface. [Enable TR069 Through Management Interface]
- Added ability to send Syslog traffic through Management Interface.[Enable Syslog Through Management Interface]
- Added support for variable on Provisioning link. [Enable using tags in the URL]
- Updated the default option of "Disable Reminder Ring for DND (P29072/29172)" to "1 - Yes".
- Optimized Syslog makes it more user-friendly.



- Add SSL Key Log File. [With Secret Key Information]
- Allow configuring devices through SSH from different networks. [Security Controls for SSH/Telnet Access]
- Added additional Flash Digit events.
- Optimized the layout of the software version on the status page to make it looks better.
- Add support of DHCP Option 150. [Additional Override DHCP Option]
- Add new special feature option "138- GIBTELECOM" (Profile1 or 2-> Special Feature-> GIBTELECOM).
- Add support for the "From Domain" option. [From Domain]
- GUI enhancement to display correctly port status.
- Added support for SRTP Key Length. [SRTP Key Length]
- Added support for Inband DTMF Duration. [Inband DTMF Duration]
- Added support for DSP DTMF Detector Duration Threshold. [DSP DTMF Detector Duration Threshold]
- Added support following up not on WebUI pvalues:
 - P61701/61702 TR-069 firewall rules (Value Range:1-65535, no default)
 - P8603 Root CA Version (0 Current Root; 1 New Root, default is 1)
 - P8604 Provision and upgrade to new Gen-2 certificate. (1- upgrade; 0 no upgrade, default is 0).
 - P8605 Contents (text string) of Gen-2 certificate to upgrade. (String. Maxlength 8192, no default)
 - P8606 Contents (text string) of Gen-2 EC private key to upgrade. (String. Maxlength 8192, no default)
 - P8615 Disable filename in URL for config provision. (1 -Yes, 0 No, default is 0)
 - P8616 Disable filename in URL for firmware upgrade. (1 -Yes, 0 No, default is 0)

- Fixed device faxes may not be sent and received normally with specific fax machines.
- Fixed device still uses a random port for SIP registration when it's set to "No" on BroadSoft.
- Fixed device plays priority alert call waiting tone incorrectly on BroadSoft.
- Fixed device plays Alternate Number Call Waiting Tone incorrectly on BroadSoft.
- Fixed device cannot enable local call feature using certain dial plan on BroadSoft.
- Fixed a bug that causes server input not to conform to the rule.
- Fixed a bug that causes an ATA crash after calling itself.
- Fixed incorrect network information in SSH.
- Fixed retry wait time when subscribing to 403 Forbidden is always displayed in English when the language is switched.
- Fixed device cannot access the page and establish a call after unplugging and plugging the network cable while on PPPoE and OpenVPN network.
- Fixed device cannot config "OpenVPN Transport" via TR069.
- Fixed HT818 did not use ACS URL passed in DHCP option.
- Fixed device didn't send HTTP to ACS if only IPV6 in WIFI.
- Fixed device OUI reported by CPE mismatch with real OUI in MAC address.



- Fixed the Loop Current Disconnect Duration comment for Profile 2 in Chinese mode is missing the milliseconds unit.
- Fixed a bug that causes HT818 using the T38 to be not compatible with the Canon_FAX-L150 fax machine.
- Fixed an issue that causes the device still ring on DND.
- Fixed the log server domain name resolution order is incorrect.
- Fixed the bug that causes the device will not send require when the path contains "%".
- Fixed the bug that causes the device to resend the OpenVPN request process every five seconds after unplugging the network cable.
- Fixed device deleting node via ACS server will cause CPE crash.
- Fixed an error that causes a CPE crash while executing DeleteObject.
- Fixed device Audio lost when call waiting for caller ID is enabled.
- Fixed the checked state error when the Priority Header parameter is set to "Yes".
- Fixed the bug caused by Call waiting dropped by MTAS Server.
- Fixed a bug causing the Automatic Upgrade setting will restore to "No" after the device reboot.
- Fixed the status light is abnormal after the FTP upgrade fails.
- Fixed the copyright not translated into the Russian language on the Russian page.
- Fixed the bug that causes the call cannot to be resumed after pressing hold.
- Fixed device local RBT not played after 180 ringing.
- Fixed device the forced SRTP * 18 function is not effective when it is currently effective.
- Fixed device memory is OOM when the 1.0.41.2 version is changed.
- Fixed device high pitch beep present with first call waiting tone.
- Fixed a call forward fails issue on Zoom.
- Fixed device call gets ended by the server after 30 mins on hold on Zoom.
- Fixed device sends out REGISTER to 4 accounts after provisioned with 4 FXS ports info on Zoom.
- Fixed device ring tone will be abnormal if more than five ports ring at the same time.
- Fixed device when calling certain numbers, the user will get a long ringback tone.
- Fixed a bug that causes the *Distinctive Ring Tone* feature not to work in certain scenarios.
- Fixed device Jitter Buffer Type not getting used.
- Fixed device after the local three-party conference ends, the phone reports the call status as P2P.
- Fixed device after filling in the Custom Certificate with the GEN 1 certificate, sips TLS registration failed.
- Fixed device when using T38 and Canon_FAX-L150 fax machine, the fax rate is not as expected.
- Fixed device the value of custom certificate P8472 is empty after reboot.
- Fixed device RTPevent flash is not sent before a call is established.
- Fixed device If the device IP and gateway are not in the same network segment, no error will be prompted.
- Fixed device can't dial and unable to access the web during running "FAX" case.
- Fixed device after the fax is sent, no audio on both sides, and the IVR becomes invalid.
- Fixed device SSH cannot log in after factory restoration.



NEW FEATURES OVERVIEW

This section lists major new features and describes how to use them from the user's point of view.

Enable TR069 Through Management Interface

Web Configuration

Users can find the configuration section in Web -> Basic Settings.

Through Management Interface:	O No	O Yes
Enable TR069 Through Management Interface:	No	O Yes
Enable Syslog Through Management Interface:	No	O Yes

Functionality

This feature allows users to route TR069 packets through the management interface.

Pvalue	Description	Value range	Default
8607	Enable TR069 Through	0 - No	0 - No
	Management Interface	1 - Yes	

Enable Syslog Through Management Interface

• Web Configuration

Users can find the configuration section in Web -> Basic Settings.

Enable TR069 Through Management Interface:	No	O Yes	_	
Enable Syslog Through Management Interface:	No	O Yes		
Management Interface IPv4 Address:		LAN Tag [(0-4094)

Functionality

This feature allows users to route Syslog packets through the management interface.




Pvalue	Description	Value range	Default
8610	Enable Syslog Through	0 - No	0 - No
	Management Interface	1 - Yes	

Enable using tags in the URL

• Web Configuration

Users can find the configuration section in Web -> Advanced Settings.



Functionality


This feature allows users can configure variables on the configuration server path to differentiate the directories on the server.

Pvalue	Description	Value range	Default
8609	Enable using tags in the URL	0 - No	0 - No
		1 - Yes	


With Secret Key Information

• Web Configuration

Users can find the configuration section in Web -> Advanced Settings.-> Information Capture-> Capture







Functionality


This feature allows users to make packet capture including the secret key to decrypt the captured TLS packets.

Pvalue	Description	Value range	Default
22419	With Secret Key Information	0 - No	0 - No
		1 - Yes	

Security Controls for SSH/Telnet Access

• Web Configuration

Users can find the configuration section in Web -> Basic Settings.



Functionality

This feature allows users to Security Control the Pvalue for SSH or Telnet Access:

Pvalue	Description	Value range	Default
28210	Security Controls for SSH/Telnet	0 - Only allow SSH	3 - Allow any user
	Access	private IP users to set	to set any Pvalue
		system Pvalue	
		1 - Allow all SSH users to	
		set system Pvalue	
		2 - Allow all SSH users to	
		set any Pvalue	



	3 - Allow any user to set	
	any Pvalue	
	4 - Prohibit setting Pvalue	

Additional Override DHCP Option

• Web Configuration

Users can find the configuration section in Web -> Advanced Settings.

O No O Yes Additional Override DHCP Option:					
Addi	None	v V	icr Option	1.	

Functionality


This feature allows users to enable the Additional Override DHCP Option in Option 150.

Value range Default
rerride DHCP 0 – None 0 – None
1 – Option 150

From Domain

Web Configuration

Users can find the configuration section in Web -> Profile 1 or 2



Functionality

This feature allows users to add the actual domain name, it will override the from header.

Pvalue	Description	Value range	Default
8617	From Domain	String	Null
8618			



SRTP Key Length

• Web Configuration

Users can find the configuration section in Web -> Profile 1 or 2

Jitter Buffer Length:		● Low ○ Medium ○ High
	SRTP Mode:	○ Disabled ○ Enabled but not forced ○ Enabled and forced
	SRTP Key Length:	AES 128&256 bit v
188	Crypto Life Time:	O Disabled • Enabled

Functionality


This feature allows users to select supported SRTP Key Length.

Pvalue	Description	Value range	Default
2383	SRTP Key Length	0 - AES 128&256 bit	0 - AES 128&256
2483		1 - AES 128 bit	bit
		2 - AES 256 bit	

Inband DTMF Duration

Web Configuration

Users can find the configuration section in Web -> Profile 1 or 2



Functionality

This feature allows users to config the Inband DTMF Duration.

Pvalue	Description	Value range	Default
28134	Inband DTMF Duration - duration	Min: 40	100
28135		Max: 2000	
28138	Inband DTMF Duration -	Min: 40	50
28139	inter-duration	Max: 2000	



DSP DTMF Detector Duration Threshold

• Web Configuration

Users can find the configuration section in Web -> Profile 1 or 2

Inhand DTMF Duration		In 40-2000 milliseconds range, duration:	100	inter-duration:	50
		In 20-200 milliseconds range, duration:		inter-duration:	30
Disal	ble DTMF Negotiation:	O No (negotiate with peer) • Yes (use	above DTN	IF order without ne	gotiation)

Functionality

This feature allows users to config the DSP DTMF Detector Duration Threshold.

Pvalue	Description	Value range	Default
28201	DSP DTMF Detector Duration	Min: 20	30
28202	Threshold - duration	Max: 200	
28205	DSP DTMF Detector Duration	Min: 20	30
28206	Threshold - inter-duration	Max: 200	



FIRMWARE VERSION 1.0.41.5

PRODUCT NAME

HT801, HT802

DATE

09/28/2022

FIRMWARE FILE INFORMATION

HT801 firmware file name: ht801fw.bin
 MD5: 098932c01f3ac86ac9d30470bfac9ea3

HT802 firmware file name: ht802fw.bin
 MD5: 9ff71415378139defc726d63d96ade70

- Fixed audio lost issue when call waiting caller ID is enabled.
- Fixed the device is out of memory when the 1.0.41.2 version is changed.
- Fixed the status light is abnormal after FTP upgrade fails.
- Fixed device will not send request when path contains % character.



FIRMWARE VERSION 1.0.41.2

PRODUCT NAME

HT801, HT802, HT812, HT814, HT818

DATE

06/28/2022

FIRMWARE FILE INFORMATION

- HT801 firmware file name: ht801fw.bin
 MD5: 9a955a99c48193b768166a2a796c2600
- HT802 firmware file name: ht802fw.bin
 MD5: 7a73d62e47967cffcfedf4c649e0cd27
- HT812 firmware file name: ht812fw.bin
 MD5: 8c822a212fffd1542950c03370a7c9b7
- HT814 firmware file name: ht814fw.bin
 MD5: 8c822a212fffd1542950c03370a7c9b7
- HT818 firmware file name: ht818fw.bin
 MD5: 47744ad811d71aa0d9ad881785d29d88

ENHANCEMENT

• Updated Time Zone option "GMT+01:00 (Paris, Vienna, Warsaw)" to "GMT+01:00 (Paris, Vienna, Warsaw, Brussels)".

- [HT818] Fixed HT818 'Add MAC in User-Agent' option displays error in Chinese mode.
- Fixed the syslog list information will not be cleared after hard key recovery.
- Fixed device unable to set time zone to GMT+01:00 (Paris, Vienna, Warsaw).
- Fixed Second Register has no auth header by default.
- [HT818] Fixed a bug causing Real-Time Transport Protocol marker in rtpevent all True.



FIRMWARE VERSION 1.0.39.4

PRODUCT NAME

HT801, HT802, HT812, HT814, HT818

DATE

06/07/2022

FIRMWARE FILE INFORMATION

- HT801 firmware file name: ht801fw.bin
 MD5: 8cdbebb700d4c3ee7809c4b1780cc72c
- HT802 firmware file name: ht802fw.bin
 MD5: e5e430ed7a037536b00fb3d938af623a
- HT812 firmware file name: ht812fw.bin
 MD5: 399f6a6fbf043083e1cdac9a187bc811
- HT814 firmware file name: ht814fw.bin
 MD5: 399f6a6fbf043083e1cdac9a187bc811
- HT818 firmware file name: ht818fw.bin
 MD5: 775c663e2ad8a91f5984dd41eda37780

ENHANCEMENT

- Added feature to send SNMP traffic through Management Interface [Enable SNMP Through Management Interface].
- Added feature to re-subscribe only after a configurable timeout after receiving 403 [Subscribe Retry Wait Time upon 403 Forbidden].
- Added feature support e911 compliance and HELD protocol [E911/HELD Protocol].
- Updated the default value of "Maximum Number of SIP Request Retries" from 4 to 2.
- Updated CDR File Option | SIP File Option (P8534/8535) value from "1 Override" to "Overwrite".
- Updated CDR File Option | SIP File Option (P8534/8535) default value from "Keep" (0) to "Overwrite" (1).
- Added Local IVR option that announces extension number of the port.

- [HT81x] Fixed device unable to connect to TR069 server after set Enable Management Interface to Yes.
- Fixed registration request will not be sent after device restart.
- Fixed an issue causing slic driver failed to load and device does not work properly.
- Fixed HT8xx device cannot connect to local deployment environment.
- Fixed device cannot enable local call feature using certain dial plan on Broadsoft.
- Fixed HT8xx device P-Access-Network-Info Header not in Register on Broadsoft.



- Fixed "Add MAC in User-Agent" option is invalid after filling in SIP User-Agent and SIP User-Agent Postfix.
- [HT81x] Fixed device not recognizing rtpevent in DTMF.
- Fixed device plays random DTMF during conversation.
- Fixed device crashes after provision in specific scenario.
- Fixed device freezes after 1 to 2 days of normal operations.

NEW FEATURES OVERVIEW

This section lists major new features and describes how to use it from the user's point of view.

Enable SNMP Through Management Interface

• Web Configuration

User can find the configuration section in Web -> Basic Settings.

Enable Management Interface:	● No ○ Yes	
Management Access:	Management Interface Only	~
Enable SNMP Through Management Interface:	● No ○ Yes	
Management Interface IPv4 Address:	802.1Q/VLAN Tag 0 802.1p priority value 0	(0-4094)

Functionality

This feature allows users to route SNMP packets through management interface.

Pvalue	Description	Value range	Default
28209	Enable SNMP Through	0 - No	0 - No
	Management Interface	1 - Yes	

Subscribe Retry Wait Time upon 403 Forbidden

Web Configuration

User can find the configuration section in Web -> FXS or Profile

SUBSCRIBE for MWI:		 No, do not send SUBSCRIBE for Message Waiting Indication Yes, send periodical SUBSCRIBE for Message Waiting Indication 	
	Subscribe Retry Wait Time upon 403 Forbidden:	0 (0-10080 in minutes. Default is 0, max 7 days)	
	Send Anonymous:	No Yes (caller ID will be blocked if set to Yes)	

Functionality



This feature allows users to adjust the subscribe retry waiting time while it is rejected with 403 forbidden.

Pvalue	Description	Value range	Default
60068	Subscribe Retry Wait Time upon	Min: 0	0 (0-10080 in minutes.
	403 Forbidden (FXS1 or Profile1)	Max:10080	Default is 0, max 7 days)
60168	Subscribe Retry Wait Time upon	Min: 0	0 (0-10080 in minutes.
	403 Forbidden (FXS2 or Profile2)	Max:10080	Default is 0, max 7 days)

E911/HELD Protocol

• Web Configuration

User can find the configuration section in Web -> Advanced Settings.

E911/HELD Protocol:	
Enable E911:	● No ○ Yes
HELD Protocol:	• HTTP O HTTPS
HELD Synchronization Interval:	0 (in minutes. 0 (Disable) or Between 30-1440)
Location Server:	
Location Server Username:	
Location Server Password:	
Secondary Location Server:	
Secondary Location Server Username:	
Secondary Location Server Password:	



HELD Location Types:	geodetic,civic,locationURI
HELD NAI:	○ No ○ Yes
HELD Identity 1:	
HELD Identity 1 Value:	
HELD Identity 2:	
HELD Identity 2 Value:	
HELD Identity 3:	
HELD Identity 3 Value:	
HELD Identity 4:	
HELD Identity 4 Value:	
HELD Identity 5:	
HELD Identity 5 Value:	
HELD Identity 6:	
HELD Identity 6 Value:	
HELD Identity 7:	
HELD Identity 7 Value:	
HELD Identity 8:	
HELD Identity 8 Value:	
HELD Identity 9:	
HELD Identity 9 Value:	
HELD Identity 10:	
HELD Identity 10 Value:	
E911 Emergency Numbers:	911
Geolocation-Routing Header:	No ○ Yes
Priority Header:	● No ○ Yes



• Functionality

This feature allows users for e911 dialing along with HELD protocol to support location/address delivery.

Pvalue	Description	Value range Default	
8565	Enable E911	0 - No	0 - No
		1 - Yes	
8566	HELD Protocol	0 - HTTP	0 - HTTP
		1 - HTTPS.	
8567	HELD Synchronization Interval	Disable: 0	0 (in minutes. 0 (Disable)
		Min: 30	or Between 30-1440)
		Max: 1440	
8568	Location Server	Max Length - 256	Null
8569	Location Server Username	Max Length - 64	Null
8570	Location Server Password	Max Length - 64	Null
8571	Secondary Location Server	Max Length - 256	Null
8572	Secondary Location Server	Max Length - 64	Null
	Username		
8573	Secondary Location Server	Max Length - 64	Null
	Password		
8574	HELD Location Types	Max Length - 64	geodetic,civic,locationURI
8576	HELD NAI	0 – No	0 - No
		1 - Yes	
8577	HELD Identity 1	Max Length - 64	Null
8578	HELD Identity 1 Value	Max Length - 64	Null
8579	HELD Identity 2	Max Length - 64	Null
8580	HELD Identity 2 Value	Max Length - 64	Null
8581	HELD Identity 3	Max Length - 64	Null
8582	HELD Identity 3 Value	Max Length - 64	Null
8583	HELD Identity 4	Max Length - 64	Null



8584	HELD Identity 4 Value	Max Length - 64	Null
8585	HELD Identity 5	Max Length - 64	Null
8586	HELD Identity 5 Value	Max Length - 64	Null
8587	HELD Identity 6	Max Length - 64	Null
8588	HELD Identity 6 Value	Max Length - 64	Null
8589	HELD Identity 7	Max Length - 64	Null
8590	HELD Identity 7 Value	Max Length - 64	Null
8591	HELD Identity 8	Max Length - 64	Null
8592	HELD Identity 8 Value	Max Length - 64	Null
8593	HELD Identity 9	Max Length - 64	Null
8594	HELD Identity 9 Value	Max Length - 64	Null
8595	HELD Identity 10	Max Length - 64	Null
8596	HELD Identity 10 Value	Max Length - 64	Null
8597	E911 Emergency Numbers	Max Length – 64 Permitted Characters: 0-9, *, #, ;	911
8598	Geolocation-Routing Header	0 - No 1 - Yes	0 - No
8599	Priority Header	0 - No 1 - Yes	0 - No



FIRMWARE VERSION 1.0.37.1

PRODUCT NAME

HT801, HT802, HT812, HT814, HT818

DATE

03/21/2022

FIRMWARE FILE INFORMATION

- HT801 firmware file name: ht801fw.bin
 MD5: 8755aedf0c97a59157c6347cf9b66448
- HT802 firmware file name: ht802fw.bin
 MD5: 19d1d8f0cebe2d224989325aaf59ebcd
- HT812 firmware file name: ht812fw.bin
 MD5: cefd287d6648a48241285b5ef7564c1a
- HT814 firmware file name: ht814fw.bin
 MD5: cefd287d6648a48241285b5ef7564c1a
- HT818 firmware file name: ht818fw.bin
 MD5: b80bc8c0c3c0b3312b16bb421c1052c4

ENHANCEMENT

- Add feature Configuration File Types Allowed [Feature Configuration File Types Allowed].
- Add feature MAC in User-Agent [MAC in User-Agent].
- Add feature Use MAC Header [Use MAC Header].

BUG FIX

- [HT818] Fixed changing the dialing rule may cause the device fail to hook.
- Fixed the device local call features affects dial plan **x+.
- Fixed an issue causing Call Features do not take effect after device reboot.
- [HT818] Fixed devices could not answer the incoming call while change Pvalue.
- [HT81x] Fixed OpenVPN port can be set to null.
- Fixed an issue causing the system attempt to failback upon DNS query.
- Fixed Fax pass-through fails with firmware 1.0.33.4.
- Fixed "Let's Encrypt" root CA certificate could not be updated.

KNOWN ISSUES

[HT818] The Authenticate server certificate domain/chain option requires device reboot to take effect.

NEW FEATURES OVERVIEW

This section lists major new features and describes how to use it from the user's point of view.



Configuration File Types Allowed

• Web Configuration

User can find the configuration section in Web -> Advanced Settings.

 Always Check for New Firmware at Boot up Check New Firmware only when F/W pre/suffix cha Always Skip the Firmware Check 				
Configuration File Types Allowed:	All	<u> </u>		
Disable SIP NOTIFY Authentication:	No	O Yes (Device will not challenge NOTIFY with 40		

Functionality

This feature allows users to configure provision configuration file type in xml file only or all file types.

Pvalue	Description	Value range	Default
8601	Configuration File Types Allowed	47 - All	47 - All
		46 - XML only	

MAC in User-Agent

• Web Configuration

User can find the configuration section at Web -> FXS Port / Profile

SIP User-Agent Postfix:					
Add MAC in User-Agent:	No		~		
Use MAC Header:	No		~		
RFC2543 Hold:	O No	Yes			

Functionality

This feature allows users to configure "User-Agent" in the SIP header field, when this feature is set to "No", "User-Agent" does not carry a MAC, when this feature is set "Yes except REGISTER", "User-Agent" in REGISTERSIP header field does not carry MAC but other SIP packet header fields carries MAC, when this feature is set to "Yes to all SIP", "User-Agent" in the SIP packet header field will carries the MAC.

New P Values

Pvalue	Description	Value range	Default
26061	MAC in User-Agent (FXS Port 1/ Profile 1)	0 - NO	0 - NO
		1 - Yes except REGISTER	
		2 - Yes to all SIP	
26161	MAC in User-Agent (FXS Port 2/ Profile 2)	0 - NO	0 - NO
		1 - Yes except REGISTER	
		2 - Yes to all SIP	



Use MAC Header

• Web Configuration

User can find the configuration section at Web -> FXS Settings (Profile)

SIP User-Agent Postfix:			
Add MAC in User-Agent:	No	,	~
Use MAC Header:	No	~]
RFC2543 Hold:	O No	Yes	

Functionality

This feature allows users to configure MAC Header in the SIP packet header field, when this feature is set to "No", the MAC header field is not carried in the SIP packet header field, when this feature is set to "REGISTER Only", the register packet header field carries the MAC header field but the remaining SIP packets do not carry MAC header fields, when this feature is set to "Yes to all SIP", the MAC header field is carried in the SIP data packet header field.

New P Values

Pvalue	Description	Value range	Default
29090	Use MAC Header (FXS Port 1/ Profile 1)	0 - NO 1 - REGISTER Only 2 - Yes to all request SIP	0 - NO
29190	MAC in User-Agent (FXS Port 2/ Profile 2)	0 - NO 1 - REGISTER Only 2 - Yes to all request SIP	0 - NO