

GCC601X UC + Networking Convergence Solutions System Firmware Release Notes

IMPORTANT UPGRADING NOTE

- [12/6/2024] [1.0.5.5 (SYS)] Due to changes in Application Filtering, users will no longer be able to downgrade to SYS 1.0.3.x or lower and PBX 1.0.25.41 or lower after upgrading to 1.0.5.5.
- [8/21/2024] [1.0.1.34(SYS)] Supported new GCC601x models and blocked firmware downgrade to any older firmware than 1.0.1.34.
- [7/26/2024] [1.0.1.32(SYS)] Changed the default value from Enable to Disable for "Allow DHCP Option 43 and 66 to Override Server" and "Check/Download New Firmware at Bootup". Upon upgrading from older version, these two options will be disabled. Please re-enable it if needed.



Table of Content

| IMPORTANT UPGRADING NOTE | 1 |
|--|----------|
| FIRMWARE FILE DOWNLOAD | 4 |
| FIRMWARE VERSION 1.0.5.6(SYS) | 5 |
| PRODUCT NAME DATE FIRMWARE FILE INFORMATION | |
| FIRMWARE VERSION 1.0.3.6(SYS) | |
| PRODUCT NAME DATE FIRMWARE FILE INFORMATION CHANGES/ENHANCEMENT | |
| FIRMWARE VERSION 1.0.3.5(SYS) | 8 |
| PRODUCT NAME DATE FIRMWARE FILE INFORMATION CHANGES/ENHANCEMENT | 38 |
| FIRMWARE VERSION 1.0.1.34(SYS) | 10 |
| PRODUCT NAME DATE FIRMWARE FILE INFORMATION CHANGES/ENHANCEMENT | 10 |
| FIRMWARE VERSION 1.0.1.32(SYS) | 11 |
| PRODUCT NAME DATE FIRMWARE FILE INFORMATION CHANGES/ENHANCEMENT | 11 11 |
| FIRMWARE VERSION 1.0.1.10(SYS) | 12 |
| PRODUCT NAME DATE FIRMWARE FILE INFORMATION | 12 |



| CHANGES/ENHANCEMENT | 12 |
|-------------------------------|----|
| FIRMWARE VERSION 1.0.1.8(SYS) | 13 |
| PRODUCT NAME | 13 |
| DATE | 13 |
| FIRMWARE FILE INFORMATION | 13 |
| CHANGES/ENHANCEMENT | 13 |



FIRMWARE FILE DOWNLOAD

| Individual firmware | files are | available fo | r downloading | at | URL | below: |
|---------------------|-----------|--------------|---------------|----|-----|--------|
| | | | | | | |

https://www.grandstream.com/support/firmware



FIRMWARE VERSION 1.0.5.6(SYS)

PRODUCT NAME

GCC6010, GCC6010W, GCC6011

DATE

12/6/2024

FIRMWARE FILE INFORMATION

GCC601x system firmware file name: gcc601xfw.bin

MD5 checksum: 0815d1f0a1e272e6d3b6b0216aedb870

GCC601x complete firmware file name: gcc601xfullyfw.bin (Supported only starting from 1.0.3.5)

MD5 checksum: 1b19dcb30ead367939324922dbe85d20

(Including SYS 1.0.5.6 + PBX 1.0.27.14)

- [Home] Added Operation Log page.
- [Home] Added the ability to schedule regular backups under the Maintenance→Backup & Restore page.
- [Home] Added support for MTA email method.
- [Networking] Added support for load balancing strategies under the *Routing →Policy Routes* page.
- [Networking] Added support for VRRP.
- [Networking] VPN settings are now retained after closing VPN.
- [Networking] DNS filtering now supports filtering by SNI and common name in the certificate.
- [Networking] IPSec is now limited to 64 tunnels.
- [Networking] Added support for connection speed test with GWN Cloud.
- [Networking] Added support for receiving PPSK configurations from GWN Cloud.
- [Firewall] Added ability to configure outbound traffic rules under the *Firewall Policy→Traffic Rules* page.



- [Firewall] IDS/IPS detection settings will now be applied to all WAN interfaces. Interfaces can no longer be excluded.
- [Firewall] Added support for SMPT(S) and POP3(S) detection protocols.
- [Firewall] Added support for importing and exporting SSL proxy exemption lists.
- [Firewall] Added ability to schedule the automatic turning on/off of DNS filtering, web filtering, and application filtering.
- [Firewall] Added support for Geo-IP filtering.
- [Firewall] SSL exemption list now supports wildcard input.
- [Firewall] Added security log risk levels and corresponding filters.
- [Firewall] Added *Application List* tab to the [Application Filtering] section. This page will show a list of all monitored applications and their corresponding risk levels.
- [Network Nodes] Added support for 6GHz band in the SSID, Radio, and Mesh settings.
- [PBX] Added ability to assign the PBX module with an IP address outside of VLAN 1.
- [UC Endpoints] Fast Provision will now also include the PBX module's local LDAP phonebook information.
- Several bug fixes.



FIRMWARE VERSION 1.0.3.6(SYS)

PRODUCT NAME

GCC6010, GCC6010W, GCC6011

DATE

10/8/2024

FIRMWARE FILE INFORMATION

GCC601x system firmware file name: gcc601xfw.bin

MD5 checksum: 25957d6a84dd13b2976c6d08ae386221

GCC601x complete firmware file name: gcc601xfullyfw.bin (Supported only starting from 1.0.3.5)

MD5 checksum: dd0e37ef081abf11ea56151029724fc0

(Including SYS 1.0.3.6 + PBX 1.0.25.41)

- [Home] Fixed an issue that offline device disappears from Network Topology
- [Networking] Fixed an issue that on GCC6010 SFP1 only supports maximum 1G bandwidth. Now it opens to 2.5G.
- Internal bug fixes.



FIRMWARE VERSION 1.0.3.5(SYS)

PRODUCT NAME

GCC6010, GCC6010W, GCC6011

DATE

9/20/2024

FIRMWARE FILE INFORMATION

GCC601x system firmware file name: gcc601xfw.bin

MD5 checksum: bbcd081cb648443fd7e9cac33e5ff333

GCC601x complete firmware file name: gcc601xfullyfw.bin (Supported only starting from 1.0.3.5)

MD5 checksum: 89d6b124242b06bf2e82790b5929a0fc

(Including SYS 1.0.3.5 + PBX 1.0.25.40)

- [Home] Added support for formatting M.2 SSD
- [Home] Added support of Real-time Session Statistics in Overview page
- [Home] Added support of **Show Offline Device** in Topology page
- [Home] Added configuration of Redirect from Port 80 in System Settings → Security Settings → Web
 Access
- [Home] Added support of complete firmware upgrade to upgrade both System and PBX firmware by one .bin file
- [Home] Fixed the bug that prompts "internal error" when performing "Detect New Version" in firmware
 Upgrade
- [Networking] Allowed same VLAN ID configuration on different WANs
- [Networking] Changed IPv6 MTU minimum value to 1280
- [Networking] Added WAN Port MAC address configuration



- [Networking] Added **Blackhole** option for Static Routes → Outgoing Interface
- [Networking] Added **PBX Service** configurations for Traffic Management → QoS → VoIP Settings
- [Networking] Added support of batch delete to Maintenance → System Diagnostics → Core File
- [Networking] Added support of saving capture on attached storage under Maintenance → System
 Diagnostics → Capture
- [Networking] Added Takeover / Un-Takeover Switch Alert option into Maintenance → Alerts &
 Notifications → E-mail Notification Settings
- [Networking] Fixed the bug that WAN related configurations are deleted when disabling WAN
- [Networking] Enforced minimum 1 LAN port when disabling Port under Network Settings → Port
 Configuration
- [Networking] Supported exporting pem format certificate in System Settings → Certificates
- [Firewall] Added support of **Static ARP List** under Security Defense → ARP Protection
- [Firewall] Moved Spoofing Defense from DoS Defense to ARP Protection
- [Firewall] Added support of **IP Exception** to Content Control
- [Firewall] Added search feature in Content Control → Application Filtering → App Filtering Rules
- [Firewall] UI optimization
- Internal bug fixes.



FIRMWARE VERSION 1.0.1.34(SYS)

PRODUCT NAME

GCC6010, GCC6010W, GCC6011

DATE

8/21/2024

FIRMWARE FILE INFORMATION

GCC601x system firmware file name: gcc601xfw.bin

MD5 checksum: 2736f9bd5a51e24e53857546887a22ec

- Added support of new models, GCC6010W, GCC6011
- Blocked system firmware downgrade to any older version
- Internal bug fixes.



FIRMWARE VERSION 1.0.1.32(SYS)

PRODUCT NAME

GCC6010

DATE

7/26/2024

FIRMWARE FILE INFORMATION

GCC6010 system firmware file name: gcc601xfw.bin

MD5 checksum: 3b6810c23b4ee941c534649ef84d41ea

- Resolved the Tiktok Live streaming issue when Antivirus is enabled.
- Changed the default value from Enable to Disable for "Allow DHCP Option 43 and 66 to Override Server"
 and "Check/Download New Firmware at Bootup". Upon upgrade from older version, these two options
 will be disabled, please re-enable it if needed.
- Changed the default value from 10sec to 300sec for all Flood Attack Defense timeout settings.
- Changed the default action to Drop for WAN Inbound Rules under Firewall Policy.
- Updated the DPI library, latest library is not compatible with SYS version lower than 1.0.1.32.
- Updated the IPS, URL, and Antivirus signature library.
- Internal bug fixes.



FIRMWARE VERSION 1.0.1.10(SYS)

PRODUCT NAME

GCC6010

DATE

6/28/2024

FIRMWARE FILE INFORMATION

GCC6010 system firmware file name: gcc601xfw.bin

MD5 checksum: c3b812966176a904282000ab622f3011

- Disable Check/Download New Firmware at Bootup by default.
- Internal bug fixes.



FIRMWARE VERSION 1.0.1.8(SYS)

PRODUCT NAME

GCC6010

DATE

6/4/2024

FIRMWARE FILE INFORMATION

• GCC6010 system firmware file name: gcc601xfw.bin

MD5 checksum: 0294ea7965254b2e99d10a5399bfd05b

CHANGES/ENHANCEMENT

• This is the initial release of GCC6010 system firmware.