

# GSC35818HS Firmware Release Notes

## Table of Content

<b>FIRMWARE VERSION 1.0.1.15 .....</b>	<b>2</b>
PRODUCT NAME.....	2
DATE .....	2
FIRMWARE FILE INFORMATION .....	2
BUG FIX .....	2
<b>FIRMWARE VERSION 1.0.1.13 .....</b>	<b>3</b>
PRODUCT NAME.....	3
DATE .....	3
FIRMWARE FILE INFORMATION .....	3

## FIRMWARE VERSION 1.0.1.15

### PRODUCT NAME

GSC3518HS

*Boot 1.0.1.1; Core 1.0.1.2; Base 1.0.1.15; Amp 1.0.1.5*

### DATE

03/23/2026

### FIRMWARE FILE INFORMATION

- Firmware file name: gsc3518fw.bin  
MD5: 661422b86b3d2dbd2d51b919eb1310d9

### BUG FIX

- Fixed an issue where the device would constantly play a buzzing sound after powering on
- Fixed an issue where the device was reporting higher packet loss than what is actually happening to GDMS
- Fixed an issue where if you set the VLAN tag to 0, the device wouldn't send out SIP registration
- Fixed an issue where "Voice Frames per TX" for iLBC was incorrectly limited to a maximum value of 2

## **FIRMWARE VERSION 1.0.1.13**

### **PRODUCT NAME**

GSC3518HS

### **DATE**

02/04/2026

### **FIRMWARE FILE INFORMATION**

- Firmware file name: gsc3518fw.bin  
MD5: 11e3f0c55e55c2bd6e65e5049371333e

This is the Initial firmware for GSC3518HS.