

DP755 Firmware Release Notes

Table of Content

Table of Content.....	1
FIRMWARE VERSION 1.0.3.11.....	3
PRODUCT NAME.....	3
DATE	3
FIRMWARE FILE INFORMATION	3
SUPPORTED HARDWARE	3
SUMMARY OF UPDATE	4
ENHANCEMENT	4
BUG FIX	5
NEW P-VALUE	5
MODIFIED P-VALUE	5
FIRMWARE VERSION 1.0.3.8	7
PRODUCT NAME.....	7
DATE	7
FIRMWARE FILE INFORMATION	7
SUPPORTED HARDWARE	7
SUMMARY OF UPDATE	8
ENHANCEMENT	9
BUG FIX	9
NEW P-VALUE	9
MODIFIED P-VALUE	9
FIRMWARE VERSION 1.0.3.7	10
PRODUCT NAME.....	10
DATE	10
FIRMWARE FILE INFORMATION	10
SUPPORTED HARDWARE	10
SUMMARY OF UPDATE	10
ENHANCEMENT	10
BUG FIX	11
NEW P-VALUE	11
MODIFIED P-VALUE	11

FIRMWARE VERSION 1.0.3.4 12

PRODUCT NAME.....	12
DATE	12
FIRMWARE FILE INFORMATION	12
SUPPORTED HARDWARE	12
SUMMARY OF UPDATE	12
ENHANCEMENT	12
BUG FIX	13
NEW P-VALUE	13
MODIFIED P-VALUE	13

FIRMWARE VERSION 1.0.1.16 14

PRODUCT NAME.....	14
DATE	14
FIRMWARE FILE INFORMATION	14
SUPPORTED HARDWARE	14
SUMMARY OF UPDATE	14
BUG FIX	14

FIRMWARE VERSION 1.0.1.15 16

PRODUCT NAME.....	16
DATE	16
FIRMWARE FILE INFORMATION	16
SUPPORTED HARDWARE	16
SUMMARY OF UPDATE	16
BUG FIX	16

FIRMWARE VERSION 1.0.1.13 18

PRODUCT NAME.....	18
DATE	18
FIRMWARE FILE INFORMATION	18
SUPPORTED HARDWARE	18

FIRMWARE VERSION 1.0.3.11

PRODUCT NAME

DP755

BaseStation: *Boot 1.0.3.11; Core 1.0.3.11; Prog 1.0.3.11; CPE 1.0.4.107*

Handset: *1.0.19.38*

DATE

07/15/2024

FIRMWARE FILE INFORMATION

- Firmware file name: **dp755fw.bin**
MD5: 4fd1ad5928c77909bbd8e0552cf88ea5

SUPPORTED HARDWARE

BaseStation:

- *DP755 HW 1.0; 1.1*

Handsets:

- *DP730 HW 1.0; 1.1; 1.2*
- *DP722 HW 1.0; 1.1*
- *DP720 HW 1.0; 1.1; 1.2; 1.3; 1.4; 1.5; 1.6; 1.7; 1.8; 1.9; 2.0*
- *DP725 HW 1.0; 1.1; 1.2*

Relay:

- *DP760 HW 1.0; 1.1; 1.2; 1.3*

NOTE:

- **DP755 supports 10 handsets registration and 16 simultaneous calls on 8 handsets.**
- **DP755 does NOT include DP760 firmware, but can work with DP760 to extend the range.**
- **DP720/DP722 handset firmware can NOT downgrade to 1.0.19.30 or below.**
- **DP730 handset firmware can NOT downgrade to 1.0.19.15 or below.**

SUMMARY OF UPDATE

The main purpose of this release is for bug fixes and feature enhancement.

ENHANCEMENT

- Added In-call Dial Number on pressing transfer key.
- Added option to define the User-Agent.
- Added option “Return Code When Enable DND”.
- Added support for Action URL.
- Added “Mute as DND” option in webUI.
- Added the management interface feataure (ITSP)
- Added ability to handle simultaneous incoming call to BS HuntingGroup wihile handset in ringing state.
- Updated CPE to v1.0.4.107

BUG FIX

- Fixed inaccurate prompt when closing the user permission page access.
- Fixed calling non-existing numbers without call history.
- Fixed call forwarding 302 format not accepted by server (IOT).
- Fixed set VQ RTCP-XR internal report period to 5, PUBLISH send time is incorrect.
- Fixed VQ RTCP-XR alert report message sending error.
- Fixed VQ RTCP-XR collector function is missing.
- Fixed the prompt for changing password is not translated.
- Fixed termination call notification not reported after call ends.
- Fixed missing open door2 button when device calls into GDS, or in IP call.
- Fixed DP755 base connecting to DP760 for a while then power off the base, the connection status of DP760 not updated.
- Fixed occasionally, unbind Handset successfully in web but Handset still shows registration status
- Fixed modify the regular user password and new password not cleared in web after saved.
- Fixed device setting is V4 only, enable syslog on GDMS, device using V6 address in the syslog file.
- Fixed the controller displays an error after establishing 2nd call in the group.
- Fixed handset cancelling DND will not automatically connect to Intercom under PTT/Multicast.
- Fixed call out fails when the account name is set to a special character.
- Fixed DUT playing ringback tone before receiving 180 ringing.
- Fixed handset failed to dial contact number after configuring automatic off hook dialing.
- Fixed handset volume will back to default after mute/unmute the ringtone instead of keep previous configured volume.
- Fixed handset not displaying call history when initiating a new call.
- Fixed one way audio issue.
- Fixed password strength detection turned off by default
- Fixed "Enable User Web Access" by default, should be disabled by default.
- Fixed set the download and process all available configuration files to yes, the sequence of downloaded files is incorrect.
- Fixed device with static IP address without configure DNS will not obtain openVPN.
- Fixed using static IP, only management network ports are allowed and the working mode is not effective

NEW P-VALUE

- [Please refer to related configuration template change log](#)

MODIFIED P-VALUE

- [Please refer to related configuration template change log](#)

For detailed information about DP755, please refer to User Manual and Resource Center:

<https://documentation.grandstream.com/article-categories/dect-base-stations/>

FIRMWARE VERSION 1.0.3.8

PRODUCT NAME

DP755

BaseStation: *Boot 1.0.3.8; Core 1.0.3.8; Prog 1.0.3.8; CPE 1.0.4.91*
Handset: *1.0.19.34*

DATE

04/26/2024

FIRMWARE FILE INFORMATION

- Firmware file name: **dp755fw.bin**
MD5: a76261970cb2c0b1899987e0cc03897b

SUPPORTED HARDWARE

BaseStation:

- *DP755 HW 1.0; 1.1*

Handsets:

- *DP730 HW 1.0; 1.1; 1.2*
- *DP722 HW 1.0; 1.1*
- *DP720 HW 1.0; 1.1; 1.2; 1.3; 1.4; 1.5; 1.6; 1.7; 1.8; 1.9; 2.0*
- *DP725 HW 1.1A; 1.1B; 1.2A*

Relay:

- *DP760 HW 1.0; 1.1; 1.2; 1.3*

NOTE:

- **DP755 supports 10 handsets registration and 16 simultaneous calls on 8 handsets.**
- **DP755 does NOT include DP760 firmware, but can work with DP760 to extend the range.**
- **DP720/DP722 handset firmware can NOT downgrade to 1.0.19.30 or below.**
- **DP730 handset firmware can NOT downgrade to 1.0.19.15 or below.**

SUMMARY OF UPDATE

The main purpose of this release is for bug fixes and feature enhancement.

ENHANCEMENT

- Add support to increase the TX volume in handset mode
- Adjust Czech translations for Base and Handset

BUG FIX

- Disabled non-admin accounts by default
- Fixed DP7xx Handsets would have noise when only binding four handsets to the Base

NEW P-VALUE

- [Please refer to related configuration template change log](#)

MODIFIED P-VALUE

- [Please refer to related configuration template change log](#)

For detailed information about DP755, please refer to User Manual and Resource Center:
<https://documentation.grandstream.com/article-categories/dect-base-stations/>

FIRMWARE VERSION 1.0.3.7

PRODUCT NAME

DP755

BaseStation: *Boot 1.0.3.7; Core 1.0.3.7; Prog 1.0.3.7; CPE 1.0.4.91*
Handset: *1.0.19.31*

DATE

04/08/2024

FIRMWARE FILE INFORMATION

- Firmware file name: **dp755fw.bin**
MD5: fe8cca3597619d29861e75997db46581

SUPPORTED HARDWARE

BaseStation:

- *DP755 HW 1.0; 1.1*

Handsets:

- *DP730 HW 1.0; 1.1; 1.2*
- *DP722 HW 1.0; 1.1*
- *DP720 HW 1.0; 1.1; 1.2; 1.3; 1.4; 1.5; 1.6; 1.7; 1.8; 1.9; 2.0*

Relay:

- *DP760 HW 1.0; 1.1; 1.2; 1.3*

NOTE:

- **DP755 supports 10 handsets registration and 16 simultaneous calls on 8 handsets.**
- **DP755 does NOT include DP760 firmware, but can work with DP760 to extend the range.**
- **DP720/DP722 handset firmware can NOT downgrade to 1.0.19.30 or below.**
- **DP730 handset firmware can NOT downgrade to 1.0.19.15 or below.**

SUMMARY OF UPDATE

The main purpose of this release is for bug fixes and feature enhancement.

ENHANCEMENT

- WebUI wording update for DNS SRV Failover
- Changed “Maximum Number of SIP Request Retries” default value to 2
- Added option to save syslog settings and internal logs after factory reset
- Added the management interface feature

- Added support to allow “https://” in Config Server Path

BUG FIX

- Fixed DP755 Option A button malfunctioned when holding one party in meeting the other hung up.
- Fixed during meeting when hold phone B and C hung up, the phone A would not display hold status.
- Fixed during SIP calls when both parties are silent a sound similar to firecracker can be heard.
- Fixed connecting DP760 repeater and idle for a while then power off the Base, the connection status of DP760 would not update.
- Fixed DP755 falling into rebooting cycle after changed to a particular language.
- Fixed device prompt “line busy” when the number called not matched dialplan.
- Fixed “missed call” displayed on the handset when another phone in the ring group picked up the call.
- Fixed DP72x handset stopped working after automatic upgrade.

NEW P-VALUE

- [Please refer to related configuration template change log](#)

MODIFIED P-VALUE

- [Please refer to related configuration template change log](#)

For detailed information about DP755, please refer to User Manual and Resource Center:

<https://documentation.grandstream.com/article-categories/dect-base-stations/>

FIRMWARE VERSION 1.0.3.4

PRODUCT NAME

DP755

BaseStation: *Boot 1.0.3.4; Core 1.0.3.4; Prog 1.0.3.4; CPE 1.0.4.87*
Handset: *1.0.19.26*

DATE

1/25/2024

FIRMWARE FILE INFORMATION

- Firmware file name: **dp755fw.bin**
MD5: 0d719c5efe2f58144211f4163661d9e9

SUPPORTED HARDWARE

BaseStation:

- *DP755 HW 1.0; 1.1*

Handsets:

- *DP730 HW 1.0; 1.1; 1.2*
- *DP722 HW 1.0; 1.1*
- *DP720 HW 1.0; 1.1; 1.2; 1.3; 1.4; 1.5; 1.6; 1.7; 1.8; 1.9; 2.0*

Relay:

- *DP760 HW 1.0; 1.1; 1.2; 1.3*

NOTE:

- **DP755 supports 10 handsets registration and 16 simultaneous calls on 8 handsets.**
- **DP755 does NOT include DP760 firmware, but can work with DP760 to extend the range.**
- **Handset firmware can NOT downgrade to 1.0.19.15 or below.**

SUMMARY OF UPDATE

The main purpose of this release is for bug fixes and feature enhancement.

ENHANCEMENT

- Added "Capture" options under Syslog
- Added "With Secret Key Information" under Packet Capture
- Default ringtone changed to Ring 8
- Set to disable "menu timeout" option by default [Telstra]
- Added ability to configure HTTP/HTTPS username and password from handset for provisioning.

- Added support for multiple XSI directories per SIP account [T-Mobile]
- Added support for XSI call log history [Broadsoft]
- Added support for multicast PTT feature

BUG FIX

- Fixed DP752 fail as caller (got 500 error) when TCP/TLS enabled [Metaswitch IOT]
- Fixed DP755 not play recorded tone after receiving “484 address incomplete” [Metaswitch IOT]
- Fixed DP755 fails to provision due to DP720 not popup for username/password input [Metaswitch IOT]
- Fixed DP755 missing web UI option for DNS SRV Failover [BroadSoft R23 IOT]
- Fixed device details cannot be loaded and displayed in GDMS
- Fixed after binding new base failure, the already bound base name will be replaced with failed base
- Fixed call automatically hung up when multiple three-party conferences established.
- Fixed the value range of configuration items in Account 17-20 is different with Account 1-16.
- Fixed device continuously generate core files.
- Fixed the handset upgraded successfully but the displayed version not upgraded still the old one.
- Fixed the device failed to capture packets under IPv6 environment.
- Fixed the device failed to get IP address when the P value of network is modified in GDMS but with a space added in the value.
- Fixed HTTP provisioning not triggered in the handset after reset and subscribed the 1st time [Telstra]
- Fixed the handset may stuck if under an auxiliary call and when PTT is pressed.
- Fixed the device/account no update still shows online even if it already disconnected from network.

NEW P-VALUE

- [Please refer to related configuration template change log](#)

MODIFIED P-VALUE

- [Please refer to related configuration template change log](#)

For detailed information about DP755, please refer to User Manual and Resource Center:
<https://documentation.grandstream.com/article-categories/dect-base-stations/>

FIRMWARE VERSION 1.0.1.16

PRODUCT NAME

DP755

BaseStation: *Boot 1.0.1.16; Core 1.0.1.16; Prog 1.0.1.16; CPE 1.0.4.75*
Handset: *1.0.19.16*

DATE

11/21/2023

FIRMWARE FILE INFORMATION

- Firmware file name: **dp755fw.bin**
MD5: 0f3d7b373037441a8d772970ab0c0bdb

SUPPORTED HARDWARE

BaseStation:

- *DP755 HW 1.0; 1.1*

Handsets:

- *DP730 HW 1.0; 1.1; 1.2*
- *DP722 HW 1.0; 1.1*
- *DP720 HW 1.0; 1.1; 1.2; 1.3; 1.4; 1.5; 1.6; 1.7; 1.8; 1.9; 2.0*

Relay:

- *DP760 HW 1.0; 1.1; 1.2; 1.3*

NOTE:

- **DP755 supports 10 handsets registration and 16 simultaneous calls on 8 handsets.**
- **DP755 does NOT include DP760 firmware, but can work with DP760 to extend the range.**
- **Handset firmware can NOT downgrade to 1.0.19.15 or below.**

SUMMARY OF UPDATE

The main purpose of this release is for bug fixes.

BUG FIX

- Fixed TR069 registration information SIP server on the account status page not updated immediately
- Fixed using vocoder G.722 the background noise is very loud
- Fixed some options not restored to default values after handset factory reset
- Fixed the account status of HS1 wrongly flashed in the webUI during intercom

- Fixed group ringer HS display error
- Fixed inaccurate prompt after closing the user permission page access
- Fixed set to IPv6 only but an IPv4 address will randomly appear after long standby
- Fixed Metaswitch IOT related bugs.
- Fixed RTP Payload Type displayed error messages in IETF of G726-32 packing mode

For detailed information about DP755, please refer to User Manual and Resource Center:

<https://documentation.grandstream.com/article-categories/dect-base-stations/>

FIRMWARE VERSION 1.0.1.15

PRODUCT NAME

DP755

BaseStation: *Boot 1.0.1.15; Core 1.0.1.15; Prog 1.0.1.15; CPE 1.0.4.75*
Handset: *1.0.19.16*

DATE

10/16/2023

FIRMWARE FILE INFORMATION

- Firmware file name: **dp755fw.bin**
MD5: 7452c1f403cff911b515012179da647c

SUPPORTED HARDWARE

BaseStation:

- *DP755 HW 1.0; 1.1*

Handsets:

- *DP730 HW 1.0; 1.1; 1.2*
- *DP722 HW 1.0; 1.1*
- *DP720 HW 1.0; 1.1; 1.2; 1.3; 1.4; 1.5; 1.6; 1.7; 1.8; 1.9; 2.0*

Relay:

- *DP760 HW 1.0; 1.1; 1.2; 1.3*

NOTE:

- **DP755 supports 10 handsets registration and 16 simultaneous calls on 8 handsets.**
- **DP755 does NOT include DP760 firmware, but can work with DP760 to extend the range.**
- **Handset firmware can NOT downgrade to 1.0.19.15 or below.**

SUMMARY OF UPDATE

The main purpose of this release is bug fixes for initial released firmware 1.0.1.13.

BUG FIX

- Fixed TR069 registration information SIP server on the account status page not updated immediately
- Fixed using vocoder G.722 the background noise is very loud
- Fixed some options not restored to default values after handset factory reset
- Fixed the account status of HS1 wrongly flashed in the webUI during intercom
- Fixed group ringer HS display error

- Fixed inaccurate prompt after closing the user permission page access
- Fixed set to IPv6 only but an IPv4 address will randomly appear after long standby
- Fixed Metaswitch IOT related bugs.
- Fixed RTP Payload Type displayed error messages in IETF of G726-32 packing mode

For detailed information about DP755, please refer to User Manual and Resource Center:

<https://documentation.grandstream.com/article-categories/dect-base-stations/>

FIRMWARE VERSION 1.0.1.13

PRODUCT NAME

DP755

BaseStation: *Boot 1.0.1.13; Core 1.0.1.13; Prog 1.0.1.13; CPE 1.0.4.72*
Handset: *1.0.19.15*

DATE

09/25/2023

FIRMWARE FILE INFORMATION

- Firmware file name: **dp755fw.bin**
MD5: 84381f13876b84b67c6678781e80d897
- **FW1.0.1.13 is the INITIAL launching firmware for DP755**

SUPPORTED HARDWARE

BaseStation:

- *DP755 HW 1.0; 1.1*

Handsets:

- *DP730 HW 1.0; 1.1; 1.2*
- *DP722 HW 1.0; 1.1*
- *DP720 HW 1.0; 1.1; 1.2; 1.3; 1.4; 1.5; 1.6; 1.7; 1.8; 1.9; 2.0*

Relay:

- *DP760 HW 1.0; 1.1; 1.2; 1.3*

NOTE:

- **DP755 supports 10 handsets registration and 16 simultaneous calls on 8 handsets.**
- **DP755 does NOT include DP760 firmware, but can work with DP760 to extend the range.**

For detailed information about DP755, please refer to User Manual and Resource Center:
<https://documentation.grandstream.com/article-categories/dect-base-stations/>