

GHP630/630W/631/631W

FIRMWARE RELEASE NOTES

TABLE OF CONTENT

FIRMWARE VERSION 1.0.1.52	2
PRODUCT NAME	2
DATE	2
COMPONENT VERSIONS	2
FIRMWARE FILE INFORMATION	2
CHANGES SINCE FIRMWARE VERSION 1.0.1.50	2
<i>BUG FIXES</i>	2
PREVIOUS FIRMWARE VERSIONS	3

FIRMWARE VERSION 1.0.1.52

PRODUCT NAME

GHP630, GHP630W, GHP631, GHP631W

DATE

10/16/2026

COMPONENT VERSIONS

Boot 1.0.1.1; Base 1.0.1.52; Prog 1.0.1.52; GUI 1.0.1.52

FIRMWARE FILE INFORMATION

- Firmware file name: ghp630fw.bin
MD5: 76c7b2f299a17b8586dd7a05d0916a02

CHANGES SINCE FIRMWARE VERSION 1.0.1.50

BUG FIXES

- Fixed the issue that device failed to reconnect to default SSID after provisioning and reboot.
- Fixed the issue that device showing "Abnormal Registration" status on GDMS.
- Fixed the issue that device has low or delayed audio transmission at call start.
- Added RFC8760 support

PREVIOUS FIRMWARE VERSIONS

Version	Date	Firmware Information
1.0.1.50	12/29/2025	Release Notes
1.0.1.45	09/29/2025	Release Notes
1.0.1.41	04/02/2025	Release Notes
1.0.1.40	02/12/2025	Release Notes
1.0.1.28	10/30/2024	Release Notes
1.0.1.26	08/12/2024	Release Notes
1.0.1.24	05/17/2024	Release Notes
1.0.1.23	04/17/2024	Release Notes
1.0.1.13	03/20/2024	