

GSC35x6 Firmware Release Notes

Table of Content

FIRMWARE VERSION 1.0.3.4	2
PRODUCT NAME.....	2
DATE	2
FIRMWARE FILE INFORMATION	2
CHANGES SINCE FIRMWARE VERSION 1.0.1.29	2
<i>ENHANCEMENT</i>	2
<i>BUG FIX</i>	2

FIRMWARE VERSION 1.0.3.4

PRODUCT NAME

GSC3506/GSC3516

DATE

04/03/2023

FIRMWARE FILE INFORMATION

- Firmware file name: gsc3516fw.bin
- MD5: 24e92e04213031b8e2a3b9ff92cd48e7

CHANGES SINCE FIRMWARE VERSION 1.0.1.29

ENHANCEMENT

- Remove start and end of multicast tones

BUG FIX

- Fixed issue where multiple master devices can exist in the same environment
- Fixed issue where IP calls using IPv6 wouldn't work
- Fixed issue where music would restart mid play if played after the device reboots
- Fixed issue where RTCP reports would not be sent if you didn't specify which port to send it to
- Fixed issue where the device could get an IP address from a tagged VLAN and untagged VLAN at the same time
- Fixed issue where error prompt didn't display when entering a multicast listening address that doesn't match the requirements
- Fixed issue with account swap when swapping with an account from 1-6 and an account from 7-16
- Fixed issue where music files with commas in their name couldn't be played
- Fixed issue where you couldn't get an IP address when using PPPoE and VLAN
- Fixed issue where you couldn't get the time in an IPv6 environment
- Fixed issue where greylist password constraints weren't strict enough
- Fixed issue where if a contact name is too long, it will be displayed as 2 separate calls instead of 1 call
- Fixed issue where if you switch away from the Music page while playing Online Music, the Web UI eventually times out and the music stops playing