

# GSC35x6 Firmware Release Notes

## Table of Content

<b>FIRMWARE VERSION 1.0.3.8 .....</b>	<b>2</b>
PRODUCT NAME.....	2
DATE .....	2
FIRMWARE FILE INFORMATION .....	2
CHANGES SINCE FIRMWARE VERSION 1.0.3.4.....	2
<i>ENHANCEMENT</i> .....	2
<i>BUG FIX</i> .....	2
NEW FEATURES OVERVIEW .....	2
<i>GSC ASSISTANT</i> .....	2
<b>FIRMWARE VERSION 1.0.3.4 .....</b>	<b>4</b>
PRODUCT NAME.....	4
DATE .....	4
FIRMWARE FILE INFORMATION .....	4
CHANGES SINCE FIRMWARE VERSION 1.0.1.29.....	4
<i>ENHANCEMENT</i> .....	4
<i>BUG FIX</i> .....	4

# FIRMWARE VERSION 1.0.3.8

## PRODUCT NAME

GSC3506/GSC3516

## DATE

06/16/2023

## FIRMWARE FILE INFORMATION

- Firmware file name: gsc3516fw.bin
- MD5: 0784d0cbb9c511350ef567606c8ade7c

## CHANGES SINCE FIRMWARE VERSION 1.0.3.4

### ENHANCEMENT

- Updated English Web UI strings
- Added support for GSC Assistant[GSC ASSISTANT]
- Removed Web UI settings that weren't applicable

### BUG FIX

- Fixed an issue where GSC wouldn't automatically reconnect to a paired BT device after it has disconnected
- Fixed an issue where GDMS wouldn't be notified of a failed firmware upgrade
- Fixed an issue where after setting the BT visibility timeout to Never and rebooting the device, the device wouldn't flash blue to indicate it is visible to other devices
- Fixed an issue where the SSH tunnel to the device will show it is still up even though it has expired

## NEW FEATURES OVERVIEW

This section lists major new features and describes how to use it from the user's point of view.

### GSC ASSISTANT

- **Web Configuration**  
This option can be found on the web UI under Application -> GSC Assistant

Managed by GSC Assistant App 

Device Label 

- **Functionality**  
Configures the ability for the device to be detectable by the GSC Assistant App and what label It shows up with during the scan
- **P-Value**

<b>P-Value</b>	<b>Description</b>	<b>Value Range</b>	<b>Default</b>
22518	Managed by GSC Assistant App	0 – No 1 - Yes	1 - Yes
22519	Device Label	String	

## FIRMWARE VERSION 1.0.3.4

### PRODUCT NAME

GSC3506/GSC3516

### DATE

04/03/2023

### FIRMWARE FILE INFORMATION

- Firmware file name: gsc3516fw.bin
- MD5: 24e92e04213031b8e2a3b9ff92cd48e7

### CHANGES SINCE FIRMWARE VERSION 1.0.1.29

#### ENHANCEMENT

- Remove start and end of multicast tones

#### BUG FIX

- Fixed issue where multiple master devices can exist in the same environment
- Fixed issue where IP calls using IPv6 wouldn't work
- Fixed issue where music would restart mid play if played after the device reboots
- Fixed issue where RTCP reports would not be sent if you didn't specify which port to send it to
- Fixed issue where the device could get an IP address from a tagged VLAN and untagged VLAN at the same time
- Fixed issue where error prompt didn't display when entering a multicast listening address that doesn't match the requirements
- Fixed issue with account swap when swapping with an account from 1-6 and an account from 7-16
- Fixed issue where music files with commas in their name couldn't be played
- Fixed issue where you couldn't get an IP address when using PPPoE and VLAN
- Fixed issue where you couldn't get the time in an IPv6 environment
- Fixed issue where greylist password constraints weren't strict enough
- Fixed issue where if a contact name is too long, it will be displayed as 2 separate calls instead of 1 call
- Fixed issue where if you switch away from the Music page while playing Online Music, the Web UI eventually times out and the music stops playing