

# **WP856 Firmware Release Notes**

## **IMPORTANT UPGRADING NOTE**

## Table of Content

<b>IMPORTANT UPGRADING NOTE.....</b>	<b>1</b>
<b>WP856 FIRMWARE VERSION 1.0.1.11.....</b>	<b>3</b>
PRODUCT NAME.....	3
DATE.....	3
FIRMWARE FILE INFORMATION.....	3
KNOWN ISSUES.....	3

# WP856 FIRMWARE VERSION 1.0.1.11

## PRODUCT NAME

WP856

## DATE

02/13/2025

## FIRMWARE FILE INFORMATION

- WP856 firmware file name: wp856fw.bin  
MD5: 8d33c9a272750e5d42f0ef3028b6d342

This is the initial firmware for WP856.

## KNOWN ISSUES

Issue 1: Wi-Fi switch is not turned on automatically after factory reset via GDMS

**Solution:** Users need to manually enable the WiFi switch from GS Settings -> Network Settings -> Internet.

Issue 2: CPE CA certificate cannot be restored after factory reset via GDMS

**Solution:** Please update the "CPEService V1.0.2" in the GS Installer app. The service takes effect automatically after updating and there is no need to open it manually.

Issue 3: Call quality cannot be reported after factory reset via GDMS

**Solution:** To take effect, the device needs a reboot, or any settings change that is saved and applied from web UI.

Issue 4: Incorrect CPU information displayed in the system status on the GDMS platform. This will be resolved in the next firmware release.