GWN7672 Firmware Release Notes

IMPORTANT UPGRADING NOTE

Table of Content

IMPORTANT UPGRADING NOTE 1

FIRMWARE FILE DOWNLOAD 4

[11/10/2026] FIRMWARE VERSION 1.0.29.7 5

PRODUCT NAME 5
DATE 5
FIRMWARE FILE INFORMATION 5
CHANGES/ENHANCEMENT 5

[09/14/2026] FIRMWARE VERSION 1.0.27.20 6

PRODUCT NAME 6
DATE 6
FIRMWARE FILE INFORMATION 6
CHANGES/ENHANCEMENT 6

[08/03/2026] FIRMWARE VERSION 1.0.27.17 (BETA ONLY) 7

PRODUCT NAME 7
DATE 7
FIRMWARE FILE INFORMATION 7
CHANGES/ENHANCEMENT 7

[03/31/2026] FIRMWARE VERSION 1.0.25.18 8

PRODUCT NAME 8
DATE 8
FIRMWARE FILE INFORMATION 8
CHANGES/ENHANCEMENT 8

[02/06/2026] FIRMWARE VERSION 1.0.25.15 9

PRODUCT NAME 9
DATE 9
FIRMWARE FILE INFORMATION 9
CHANGES/ENHANCEMENT 9

[08/28/2025] FIRMWARE VERSION 1.0.25.13 10

PRODUCT NAME 10
DATE 10
FIRMWARE FILE INFORMATION 10

CHANGES/ENHANCEMENT 10
[07/10/2025] FIRMWARE VERSION 1.0.25.9 11
PRODUCT NAME 11
DATE 11
FIRMWARE FILE INFORMATION 11
CHANGES/ENHANCEMENT 11

FIRMWARE FILE DOWNLOAD

Individual firmware files are available for downloading at URL below:
https://www.grandstream.com/support/firmware

[11/10/2026] FIRMWARE VERSION 1.0.29.7

PRODUCT NAME

GWN7672

DATE

11/10/2026

FIRMWARE FILE INFORMATION

- GWN7672 Firmware file name: gwn7672fw.bin
  MD5 checksum: db4b8e5658eb776585b79df047cb6fb0

CHANGES/ENHANCEMENT

- Added Cloud Intelligent Diagnostics.
- Optimized log formatting for AI analysis.
- Optimized Radio Resource Management (RRM).
- Optimized PPSK functionality.
- Added a WLAN hardware acceleration toggle.
- Fixed an IPv4 option use-after-free vulnerability (CVE-2026-98432).
- Fixed AP generating core files on firmware 1.0.25.9.
- Fixed inbound firewall rules failing to block SSH access.
- Fixed IPv6 HTTPS connectivity when MLO is enabled.
- Fixed incorrect destination MAC address rewriting for IPv6 multicast traffic (mDNS and ICMPv6).

[09/14/2026] FIRMWARE VERSION 1.0.27.20

PRODUCT NAME

GWN7672

DATE

09/14/2026

FIRMWARE FILE INFORMATION

- GWN7672 Firmware file name: gwn7672fw.bin
  MD5 checksum: 11c424414d63de37ee283c4cacb31cfc

CHANGES/ENHANCEMENT

- Added MAC address format configuration for MAC authentication.
- Added System Debug support for Cloud management.
- Added Microsoft 365 authentication support for Captive Portal.
- Added Wi-Fi Extension support.
- Added security version information.
- Optimized One-Key Debug with encryption support and renamed it to System Debug.
- Added packet capture support through the slave AP web interface.
- Added Bluetooth scan reporting for Cloud management.
- Added diagnostic tools (Diagnosis).
- Added a RADIUS NAS ID configuration option.
- Added Fast SSID Creation.
- Added 2.4 GHz and dual-band 2.4 GHz/5GHz mesh support.
- Optimized RRM scanning.
- Added OWE support.
- Added Easy PSK support.
- Added IPSG (IP Source Guard).
- Added Network Health monitoring for Cloud management.
- Fixed fast roaming failures.
- Internal bug fixes.

[08/03/2026] FIRMWARE VERSION 1.0.27.17 (BETA ONLY)

PRODUCT NAME

GWN7672

DATE

08/03/2026

FIRMWARE FILE INFORMATION

- GWN7672 Firmware file name: gwn7672fw.bin
  MD5 checksum: 3f46e900c0e9df81afb5d08c902740d2

CHANGES/ENHANCEMENT

- Added Cloud Network Health support
- Added IPSG (IP Source Guard)
- Optimized WPA2/WPA3 PPSK handling during initial connection

[03/31/2026] FIRMWARE VERSION 1.0.25.18

PRODUCT NAME

GWN7672

DATE

03/31/2026

FIRMWARE FILE INFORMATION

- GWN7672 Firmware file name: gwn7672fw.bin
  MD5 checksum: cc272e45263d495d0a57cedc6a99f1e5

CHANGES/ENHANCEMENT

- Fixed the SSID configuration page is missing the MLO feature.
- Fixed ESSID is null after AP enabled radio schedule and reboot.
- Fixed after enabling channel scanning, the 2.4G network card keeps restarting.
- Fixed channel scanning is scheduled, and the configuration remains after the reservation is switched.
- Fixed the delete button for a selected reservation does not remain grayed out, after RRM is enabled for reservations
- Fixed 6GRRM scanning is enabled. Connect the terminal within 10 minutes; scanning cannot be triggered after 10 minutes.
- Fixed low 320Mhz wireless performance.
- Fixed 6G calibration failed.
- Fixed Boot version shows an error.
- Fixed Wi-Fi temperature reading error.
- Added RRM scan support
- Internal bug fixes.

[02/06/2026] FIRMWARE VERSION 1.0.25.15

PRODUCT NAME

GWN7672

DATE

02/06/2026

FIRMWARE FILE INFORMATION

- GWN7672 Firmware file name: gwn7672fw.bin
  MD5 checksum: bfb31e81513bbf352205672ad3b55e7d

CHANGES/ENHANCEMENT

- Updated security version.
- Internal bug fixes.

[08/28/2025] FIRMWARE VERSION 1.0.25.13

PRODUCT NAME

GWN7672

DATE

08/28/2025

FIRMWARE FILE INFORMATION

- GWN7672 Firmware file name: gwn7672fw.bin
  MD5 checksum: e27ba27542efe50f85a95b4fcea6449a

CHANGES/ENHANCEMENT

- Internal bug fixes.

[07/10/2025] FIRMWARE VERSION 1.0.25.9

PRODUCT NAME

GWN7672

DATE

07/10/2025

FIRMWARE FILE INFORMATION

- GWN7672 Firmware file name: gwn7672fw.bin
  MD5 checksum: 0e59c7271a10aa395d00a405176f7c35

CHANGES/ENHANCEMENT

- This is the initial release for GWN7672