GXW4216/GXW4224/GXW4232/GXW4248

FIRMWARE RELEASE NOTES

IMPORTANT UPGRADING NOTE

Hardware	Firmware Version	Restrictions and Cautions
GXW4248 V1.4A V1.6A	1.0.23.2+	Cannot be downgraded to firmware 1.0.23.1 or earlier version.
GXW4216/GXW4224/GXW4232 V3.0B	1.0.21.x+	Cannot be downgraded to firmware 1.0.19.4 or earlier version.
GXW4216/GXW4224/GXW4232 V2.5A GXW4248 V1.3A	1.0.17.x+	Cannot be downgraded to firmware 1.0.15.2 or earlier version.
GXW4224/GXW4232 V2.4C GXW4248 V1.2C	1.0.7.x+	Cannot be downgraded to firmware 1.0.5.43 or earlier version.

TABLE OF CONTENT

IMPORTANT UPGRADING NOTE.....1

FIRMWARE VERSION 1.0.23.17 3

PRODUCT NAME.....3
DATE.....3
COMPONENT VERSIONS.....3
FIRMWARE FILE INFORMATION.....3
CHANGES SINCE FIRMWARE VERSION 1.0.23.16.....3
ENHANCEMENTS.....*3*
BUG FIXES.....*3*

FIRMWARE VERSION 1.0.23.16 (BETA ONLY)..... 4

PRODUCT NAME.....4
DATE.....4
COMPONENT VERSIONS.....4
FIRMWARE FILE INFORMATION.....4
CHANGES SINCE FIRMWARE VERSION 1.0.23.15.....4
ENHANCEMENTS.....*4*
BUG FIXES.....*4*

PREVIOUS FIRMWARE VERSIONS 5

FIRMWARE VERSION 1.0.23.17

PRODUCT NAME

GXW4216, GXW4224, GXW4232, GXW4248

DATE

11/13/2026

COMPONENT VERSIONS

Prog: 1.0.23.17; Core: 1.0.23.6; Base: 1.0.23.14; Boot: 1.0.23.1; Recover: 1.0.23.4; CPE: 1.0.4.29

FIRMWARE FILE INFORMATION

- GXW4216 firmware file name: gxw4216fw.bin
  MD5: 320ec014c7c7c459c11dd9520375e04f
- GXW4224 firmware file name: gxw4224fw.bin
  MD5: 6ed0494a42e3de60562cd94e9c00f8e5
- GXW4232 firmware file name: gxw4232fw.bin
  MD5: 8526596ecec85fbddb5777915087d388
- GXW4248 firmware file name: gxw4248fw.bin
  MD5: 892f3c2305ebf0cf1865f0fc95aef07d

CHANGES SINCE FIRMWARE VERSION 1.0.23.16

ENHANCEMENTS

- Improved system security.

BUG FIXES

- Fixed an issue where the GXW42xx did not send multicast frames with a multicast MAC address.

FIRMWARE VERSION 1.0.23.16 (BETA ONLY)

PRODUCT NAME

GXW4216, GXW4224, GXW4232, GXW4248

DATE

10/19/2026

COMPONENT VERSIONS

Prog: 1.0.23.16; Core: 1.0.23.6; Base: 1.0.23.13; Boot: 1.0.23.1; Recover: 1.0.23.4; CPE: 1.0.4.29

FIRMWARE FILE INFORMATION

- GXW4216 firmware file name: gxw4216fw.bin
  MD5: 43b61b6df642020ab1bc3183c7f06b66
- GXW4224 firmware file name: gxw4224fw.bin
  MD5: ba85fd96f63881ed98ed07f8ad426604
- GXW4232 firmware file name: gxw4232fw.bin
  MD5: d42a7860f5606afce07085c1670837cc
- GXW4248 firmware file name: gxw4248fw.bin
  MD5: 1848f2de878636f9d7eadc2f4f91cd1d

CHANGES SINCE FIRMWARE VERSION 1.0.23.15

ENHANCEMENTS

- Improved system security.

BUG FIXES

- Fixed an issue where the “Disable Call Waiting” setting was not correctly applied when changing the FXS profile.
- Fixed an issue where Let’s Encrypt certificates provisioning failed on Telavox due to outdated built-in CA certificate list.

PREVIOUS FIRMWARE VERSIONS

Version	Date	Firmware Information
1.0.23.15	07/08/2026	Release Notes
1.0.23.11	08/14/2025	Release Notes
1.0.23.9	10/22/2024	Release Notes
1.0.23.8	04/26/2024	Release Notes
1.0.23.7	01/26/2024	Release Notes
1.0.23.6	02/23/2023	Release Notes
1.0.23.5	09/23/2022	Release Notes
1.0.23.2	12/09/2021	Release Notes
1.0.21.1	09/07/2021	Release Notes
1.0.19.4	08/04/2021	Release Notes
1.0.17.4	04/09/2021	Release Notes
1.0.15.2	02/26/2021	Release Notes
1.0.14.2	01/13/2021	
1.0.13.3	12/16/2020	Release Notes
1.0.11.3	09/17/2020	Release Notes
1.0.9.4	05/08/2020	Release Notes
1.0.7.10	12/10/2019	Release Notes
1.0.7.8	09/12/2019	Release Notes
1.0.7.7	07/08/2019	
1.0.7.3	04/24/2019	Release Notes
1.0.5.43	12/03/2018	Release Notes
1.0.5.36	05/29/2018	Release Notes
1.0.5.30	02/05/2018	Release Notes
1.0.5.28	11/03/2017	

Version	Date	Firmware Information
1.0.5.16	09/11/2015	
1.0.5.8	01/28/2015	
1.0.5.5	10/01/2014	
1.0.4.24	08/13/2014	
1.0.4.22	05/30/2014	
1.0.4.17	12/19/2013	
1.0.4.15	12/04/2013	
1.0.4.9	12/06/2013	
1.0.4.7	08/09/2013	
1.0.4.4	06/28/2013	
1.0.3.9	06/06/2013	