HT80X V2/HT81X V2 FIRMWARE RELEASE NOTES

IMPORTANT UPGRADING NOTE

Hardware	Firmware Version	Restrictions and Cautions
HT801 V2 HT802 V2 HT812 V2 HT814 V2 HT818 V2	1.0.9.3+	Once HT801 V2/HT802 V2/HT812 V2/HT814 V2/HT818 V2 is upgraded to firmware 1.0.9.3 or later, downgrading to 1.0.7.5 or earlier is not supported due to CPU frequency adjustments.

TABLE OF CONTENT

IMPORTANT UPGRADING NOTE 1

FIRMWARE VERSION 1.0.15.5 3

PRODUCT NAME 3
DATE 3
COMPONENT VERSIONS 3
FIRMWARE FILE INFORMATION 3
CHANGES SINCE FIRMWARE VERSION 1.0.15.3 3
ENHANCEMENT *3*

PREVIOUS FIRMWARE VERSIONS 4

FIRMWARE VERSION 1.0.15.5

PRODUCT NAME

HT801 V2, HT802 V2, HT812 V2, HT814 V2, HT818 V2

DATE

11/10/2026

COMPONENT VERSIONS

Program 1.0.15.5; Core 1.0.15.2; Base 1.0.15.5; Boot 1.0.15.2; CPE 1.0.5.47

FIRMWARE FILE INFORMATION

- HT801 V2/HT802 V2 firmware file name: ht80xv2fw.bin
  MD5: 7c4eb39abdcdddc1b441528c05c1dbbe
- HT812 V2/HT814 V2/HT818 V2 firmware file name: ht81xv2fw.bin
  MD5: b36d05c0f0e132f7abe05cd5619da9ea

CHANGES SINCE FIRMWARE VERSION 1.0.15.3

ENHANCEMENT

- Added security improvements

PREVIOUS FIRMWARE VERSIONS

Version	Date	Firmware Information
1.0.15.3	09/17/2026	Release Notes
1.0.15.1	07/21/2026	Release Notes
1.0.13.5	07/07/2026	Release Notes
1.0.11.4	04/03/2026	Release Notes
1.0.9.4	03/06/2026	
1.0.9.3	02/10/2026	Release Notes
1.0.7.5	12/25/2025	Release Notes
1.0.5.10	10/16/2025	Release Notes
1.0.5.9	08/23/2025	Release Notes
1.0.5.7	06/11/2025	Release Notes
1.0.5.5	04/02/2025	Release Notes
1.0.5.4	03/11/2025	Release Notes
1.0.5.3	02/28/2025	Release Notes
1.0.3.10	01/20/2025	Release Notes
1.0.3.8	01/09/2025	
1.0.3.5	11/22/2024	Release Notes
1.0.1.16 HT80x V2	11/01/2024	Release Notes
1.0.1.16 HT81x V2	10/23/2024	Release Notes