

GCC602X UC + Networking Convergence Solutions

System Firmware Release Notes

IMPORTANT UPGRADING NOTE

Table of Content

IMPORTANT UPGRADING NOTE	1
FIRMWARE FILE DOWNLOAD	4
FIRMWARE VERSION 1.0.7.59 (SYS).....	5
PRODUCT NAME	5
DATE	5
FIRMWARE FILE INFORMATION	5
BUG FIXING.....	5
FIRMWARE VERSION 1.0.7.57 (SYS)(BETA ONLY)	6
PRODUCT NAME	6
DATE	6
FIRMWARE FILE INFORMATION	6
CHANGES/ENHANCEMENT.....	6
BUG FIXING.....	7
FIRMWARE VERSION 1.0.7.48 (SYS).....	8
PRODUCT NAME	8
DATE	8
FIRMWARE FILE INFORMATION	8
CHANGES/ENHANCEMENT.....	8
FIRMWARE VERSION 1.0.7.46 (SYS).....	9
PRODUCT NAME	9
DATE	9
FIRMWARE FILE INFORMATION	9
BUG FIXING.....	9
FIRMWARE VERSION 1.0.7.44 (SYS).....	10
PRODUCT NAME	10
DATE	10
FIRMWARE FILE INFORMATION	10
CHANGES/ENHANCEMENT.....	10
BUG FIXING.....	13
FIRMWARE VERSION 1.0.7.32 (SYS).....	14
PRODUCT NAME	14

DATE	14
FIRMWARE FILE INFORMATION	14
CHANGES/ENHANCEMENT.....	14

FIRMWARE FILE DOWNLOAD

Individual firmware files are available for download at the URL below:

<https://www.grandstream.com/support/firmware>

FIRMWARE VERSION 1.0.7.59 (SYS)

PRODUCT NAME

GCC6020 / GCC6021

DATE

4/17/2026

FIRMWARE FILE INFORMATION

- GCC6020 system firmware file name: gcc602xfw.bin
MD5 checksum: 0b2a75859c8d36aee46b9d61be7b81b9
- GCC6020 complete firmware file name: gcc602xfullyfw.bin
MD5 checksum: 480afc92b230b71022d8aeae062e7a16
(Including SYS 1.0.7.59 + PBX 1.0.27.94)

BUG FIXING

- Fixed an issue where the Wireguard has no access in some case.
- Internal bug fixes.

FIRMWARE VERSION 1.0.7.57 (SYS)(BETA ONLY)

PRODUCT NAME

GCC6020 / GCC6021

DATE

3/18/2026


FIRMWARE FILE INFORMATION

- GCC6020 system firmware file name: gcc602xfw.bin
 MD5 checksum: 5f7167dda8db8ef0a0e23e791c330c75
- GCC6020 complete firmware file name: gcc602xfullyfw.bin
 MD5 checksum: 20459737beb23692dbfc3522a98ff6b8
 (Including SYS 1.0.7.57 + PBX 1.0.27.94)

CHANGES/ENHANCEMENT


- **Networking**

- **Network Settings → LAN → Bonjour Gateway:** Added support for Bridge mode



- **Network Nodes**

- **Clients:** Added "Identity Name" information column



- Supported number of VLAN

Model	GCC6010	GCC6011	GCC6010W	GCC6020	GCC6021
VLAN	32	128	64	256	256

BUG FIXING

- Fixed an issue where the device does not synchronize system time correctly.
- Internal bug fixes.

FIRMWARE VERSION 1.0.7.48 (SYS)

PRODUCT NAME

GCC6020 / GCC6021

DATE

11/25/2025

FIRMWARE FILE INFORMATION

- GCC6020 system firmware file name: gcc602xfw.bin
MD5 checksum: f5df37333c416a073f8e81888ccbd36b
- GCC6020 complete firmware file name: gcc602xfullyfw.bin
MD5 checksum: 01f5abcef56f7e8ea1bf4cb99a994045
(Including SYS 1.0.7.48 + PBX 1.0.27.90)

CHANGES/ENHANCEMENT

- Added support for GDMS new IPsec option “Add Router LAN address”, which will allow the router to use its own LAN address to configure local subnet for VPN.
- Added support for USB 4G/5G dongle.

FIRMWARE VERSION 1.0.7.46 (SYS)

PRODUCT NAME

GCC6020 / GCC6021

DATE

9/18/2025

FIRMWARE FILE INFORMATION

- GCC6020 system firmware file name: gcc602xfw.bin
MD5 checksum: aadc42be64c51d061f4a3cdfc7593a96
- GCC6020 complete firmware file name: gcc602xfullyfw.bin
MD5 checksum: 6a72ef8df90570dfc7e6618ac862c717
(Including SYS 1.0.7.46 + PBX 1.0.27.90)

BUG FIXING

- Internal bug fixes

FIRMWARE VERSION 1.0.7.44 (SYS)

PRODUCT NAME

GCC6020 / GCC6021

DATE


8/29/2025

FIRMWARE FILE INFORMATION


- GCC6020 system firmware file name: gcc602xfw.bin
MD5 checksum: 287e24f420c7b527adc4c0f4add15879
- GCC6020 complete firmware file name: gcc602xfullyfw.bin
MD5 checksum: 3eb4542dc9e4c871e0a6153e4256146c

CHANGES/ENHANCEMENT


- **Home**
 - **Overview** → **Basic Information**: Added Security Versions.
 - **Maintenance** → **Backup & Restore**: Added support for changing backup file name.
- **Networking**
 - **Network Settings** → **LAN** → **Static IP Binding**: Added support for VLAN setting
 - **Network Settings** → **MGMT**: Changed Default IP/Subnet to 10.252.252.252/24
 - **VPN**:
 - Added feature of **ZeroTier** VPN
 - Added **Setup Wizard** of **ZeroTier**




- Added feature of RADIUS authentication for **OpenVPN®**
 - **Traffic Management:** Changed the bandwidth limits for "Maximum Upstream Bandwidth" and "Maximum Downstream Bandwidth" to 1-10240 Mbps under **QoS** and **Bandwidth Limit**.
 - **System Settings** → **File Sharing:** Added support of microSD and SSD external device
- **Firewall**
 - **Overview:** Added switch for Enable/Disable Advanced Firewall




- **Content Control**
 - **DNS Filtering:**
 - Added VLAN configuration for web filtering and application filtering



- Added DNS Filtering configuration and Redirect Blocked Webpage configuration




- Added new feature of File filtering



- o **SSL Proxy** → **Basic Settings**: Added **Forced Proxy** and **Optional Proxy** configurations, and added

Built-in Domain Exemptions



- **Security Log:** Added filter of **Firewall Policy**
- **Network Nodes**
 - **AP Management:** Added support for GWN767x models
 - **Switch Management:** Added support for GWN771x and GWN782x models
 - **Wi-Fi Management → SSIDs:** Changed the bandwidth limits for "Maximum Upstream Bandwidth" and "Maximum Downstream Bandwidth" to 1-10240 Mbps

BUG FIXING

- Fixed a bug that causes device unable to route traffic between OpenVPN® server and OpenVPN® client.
- Fixed a bug that IPS incorrect trigger for Intrusion.
- Fixed an issue that Wireguard VPN cannot handle Domains for Endpoint address.

FIRMWARE VERSION 1.0.7.32 (SYS)

PRODUCT NAME

GCC6020 / GCC6021

DATE

6/21/2025

FIRMWARE FILE INFORMATION

- GCC6020 system firmware file name: gcc602xfw.bin
MD5 checksum: 8f3b81acbf8dfeea8b7411f87845ded5
- GCC6020 pbx firmware file name: gcc602xucm.bin
MD5 checksum: 150d0d3f2cde1b6acd1cd41f79cb9020
- GCC6020 complete firmware file name: gcc602xfullyfw.bin
MD5 checksum: 0d05c92de310747f779fda0f3de7dd34

CHANGES/ENHANCEMENT

- This is the initial release of GCC6020 system firmware.