

GCC602X UC + Networking Convergence Solutions

System Firmware Release Notes

IMPORTANT UPGRADING NOTE

Table of Content

IMPORTANT UPGRADING NOTE	1
FIRMWARE FILE DOWNLOAD	4
FIRMWARE VERSION 1.0.7.71 (SYS).....	5
PRODUCT NAME	5
DATE	5
FIRMWARE FILE INFORMATION	5
CHANGES/ENHANCEMENT.....	5
FIRMWARE VERSION 1.0.7.69 (SYS)(BETA ONLY)	6
PRODUCT NAME	6
DATE	6
FIRMWARE FILE INFORMATION	6
CHANGES/ENHANCEMENT.....	6
FIRMWARE VERSION 1.0.7.59 (SYS).....	7
PRODUCT NAME	7
DATE	7
FIRMWARE FILE INFORMATION	7
CHANGES/ENHANCEMENT.....	7
FIRMWARE VERSION 1.0.7.57 (SYS)(BETA ONLY)	8
PRODUCT NAME	8
DATE	8
FIRMWARE FILE INFORMATION	8
CHANGES/ENHANCEMENT.....	8
BUG FIXING.....	9
FIRMWARE VERSION 1.0.7.48 (SYS).....	10
PRODUCT NAME	10
DATE	10
FIRMWARE FILE INFORMATION	10
CHANGES/ENHANCEMENT.....	10
FIRMWARE VERSION 1.0.7.46 (SYS).....	11
PRODUCT NAME	11
DATE	11

FIRMWARE FILE INFORMATION	11
BUG FIXING.....	11
FIRMWARE VERSION 1.0.7.44 (SYS).....	12
PRODUCT NAME	12
DATE	12
FIRMWARE FILE INFORMATION	12
CHANGES/ENHANCEMENT.....	12
BUG FIXING.....	15
FIRMWARE VERSION 1.0.7.32 (SYS).....	16
PRODUCT NAME	16
DATE	16
FIRMWARE FILE INFORMATION	16
CHANGES/ENHANCEMENT.....	16

FIRMWARE FILE DOWNLOAD

Individual firmware files are available for download at the URL below:

<https://www.grandstream.com/support/firmware>

FIRMWARE VERSION 1.0.7.71 (SYS)

PRODUCT NAME

GCC6020 / GCC6021

DATE

8/11/2026

FIRMWARE FILE INFORMATION

- GCC6020 system firmware file name: gcc602xfw.bin
MD5 checksum: 9d1012974272b442c19af285b71f4df7
- GCC6020 complete firmware file name: gcc602xfullyfw.bin
MD5 checksum: c64b0c64e0094086e70b9f85860c1653
(Including SYS 1.0.7.71 + PBX 1.0.27.94)

CHANGES/ENHANCEMENT

- Internal bug fixes.

FIRMWARE VERSION 1.0.7.69 (SYS)(BETA ONLY)

PRODUCT NAME

GCC6020 / GCC6021

DATE

7/14/2026

FIRMWARE FILE INFORMATION

- GCC6020 system firmware file name: gcc602xfw.bin
MD5 checksum: 5216d720dace5dd3638789b23afd084e
- GCC6020 complete firmware file name: gcc602xfullyfw.bin
MD5 checksum: 54426aaaecda8d30c01ee832c3a08aca
(Including SYS 1.0.7.69 + PBX 1.0.27.94)

CHANGES/ENHANCEMENT

- Home / Networking / Firewall / Network Notes module supports permission management.
- Added LLDP info to clients list.
- Unlock GCC6021 port 25 - 27 for WAN configuration.
- Fixed an issue where the geographical location of the IP address is incorrect in Geo-IP filtering.
- Internal bug fixes.

FIRMWARE VERSION 1.0.7.59 (SYS)

PRODUCT NAME

GCC6020 / GCC6021

DATE

4/17/2026

FIRMWARE FILE INFORMATION

- GCC6020 system firmware file name: gcc602xfw.bin
MD5 checksum: 0b2a75859c8d36aee46b9d61be7b81b9
- GCC6020 complete firmware file name: gcc602xfullyfw.bin
MD5 checksum: 480afc92b230b71022d8aeae062e7a16
(Including SYS 1.0.7.59 + PBX 1.0.27.94)

CHANGES/ENHANCEMENT

- Fixed an issue where the Wireguard has no access in some case.
- Internal bug fixes.

FIRMWARE VERSION 1.0.7.57 (SYS)(BETA ONLY)

PRODUCT NAME

GCC6020 / GCC6021

DATE

3/18/2026


FIRMWARE FILE INFORMATION

- GCC6020 system firmware file name: gcc602xfw.bin
MD5 checksum: 5f7167dda8db8ef0a0e23e791c330c75
- GCC6020 complete firmware file name: gcc602xfullyfw.bin
MD5 checksum: 20459737beb23692dbfc3522a98ff6b8
(Including SYS 1.0.7.57 + PBX 1.0.27.94)

CHANGES/ENHANCEMENT


- **Networking**

- **Network Settings → LAN → Bonjour Gateway:** Added support for Bridge mode



- **Network Nodes**

- **Clients:** Added "Identity Name" information column



- **Supported number of VLAN**

Model	GCC6010	GCC6011	GCC6010W	GCC6020	GCC6021
VLAN	32	128	64	256	256

BUG FIXING

- Fixed an issue where the device does not synchronize system time correctly.
- Internal bug fixes.

FIRMWARE VERSION 1.0.7.48 (SYS)

PRODUCT NAME

GCC6020 / GCC6021

DATE

11/25/2025

FIRMWARE FILE INFORMATION

- GCC6020 system firmware file name: gcc602xfw.bin
MD5 checksum: f5df37333c416a073f8e81888ccbd36b
- GCC6020 complete firmware file name: gcc602xfullyfw.bin
MD5 checksum: 01f5abcef56f7e8ea1bf4cb99a994045
(Including SYS 1.0.7.48 + PBX 1.0.27.90)

CHANGES/ENHANCEMENT

- Added support for GDMS new IPsec option “Add Router LAN address”, which will allow the router to use its own LAN address to configure local subnet for VPN.
- Added support for USB 4G/5G dongle.

FIRMWARE VERSION 1.0.7.46 (SYS)

PRODUCT NAME

GCC6020 / GCC6021

DATE

9/18/2025

FIRMWARE FILE INFORMATION

- GCC6020 system firmware file name: gcc602xfw.bin
MD5 checksum: aadc42be64c51d061f4a3cdfc7593a96
- GCC6020 complete firmware file name: gcc602xfullyfw.bin
MD5 checksum: 6a72ef8df90570dfc7e6618ac862c717
(Including SYS 1.0.7.46 + PBX 1.0.27.90)

BUG FIXING

- Internal bug fixes

FIRMWARE VERSION 1.0.7.44 (SYS)

PRODUCT NAME

GCC6020 / GCC6021

DATE


8/29/2025

FIRMWARE FILE INFORMATION


- GCC6020 system firmware file name: gcc602xfw.bin
MD5 checksum: 287e24f420c7b527adc4c0f4add15879
- GCC6020 complete firmware file name: gcc602xfullyfw.bin
MD5 checksum: 3eb4542dc9e4c871e0a6153e4256146c

CHANGES/ENHANCEMENT


- **Home**
 - **Overview** → **Basic Information**: Added Security Versions.
 - **Maintenance** → **Backup & Restore**: Added support for changing backup file name.
- **Networking**
 - **Network Settings** → **LAN** → **Static IP Binding**: Added support for VLAN setting
 - **Network Settings** → **MGMT**: Changed Default IP/Subnet to 10.252.252.252/24
 - **VPN**:
 - Added feature of **ZeroTier** VPN
 - Added **Setup Wizard** of **ZeroTier**




- Added feature of RADIUS authentication for **OpenVPN®**
- **Traffic Management:** Changed the bandwidth limits for "Maximum Upstream Bandwidth" and "Maximum Downstream Bandwidth" to 1-10240 Mbps under **QoS** and **Bandwidth Limit**.
- **System Settings → File Sharing:** Added support of microSD and SSD external device
- **Firewall**
 - **Overview:** Added switch for Enable/Disable Advanced Firewall




- **Content Control**
 - **DNS Filtering:**
 - Added VLAN configuration for web filtering and application filtering



- Added DNS Filtering configuration and Redirect Blocked Webpage configuration




- Added new feature of File filtering



- o **SSL Proxy** → **Basic Settings**: Added **Forced Proxy** and **Optional Proxy** configurations, and added

Built-in Domain Exemptions



- **Security Log:** Added filter of **Firewall Policy**
- **Network Nodes**
 - **AP Management:** Added support for GWN767x models
 - **Switch Management:** Added support for GWN771x and GWN782x models
 - **Wi-Fi Management → SSIDs:** Changed the bandwidth limits for "Maximum Upstream Bandwidth" and "Maximum Downstream Bandwidth" to 1-10240 Mbps

BUG FIXING

- Fixed a bug that causes device unable to route traffic between OpenVPN® server and OpenVPN® client.
- Fixed a bug that IPS incorrect trigger for Intrusion.
- Fixed an issue that Wireguard VPN cannot handle Domains for Endpoint address.

FIRMWARE VERSION 1.0.7.32 (SYS)

PRODUCT NAME

GCC6020 / GCC6021

DATE

6/21/2025

FIRMWARE FILE INFORMATION

- GCC6020 system firmware file name: gcc602xfw.bin
MD5 checksum: 8f3b81acbf8dfeea8b7411f87845ded5
- GCC6020 pbx firmware file name: gcc602xucm.bin
MD5 checksum: 150d0d3f2cde1b6acd1cd41f79cb9020
- GCC6020 complete firmware file name: gcc602xfullyfw.bin
MD5 checksum: 0d05c92de310747f779fda0f3de7dd34

CHANGES/ENHANCEMENT

- This is the initial release of GCC6020 system firmware.