

DP755 Firmware Release Notes

Table of Content

Table of Content	1
FIRMWARE VERSION 1.0.1.16	2
PRODUCT NAME	2
DATE	2
FIRMWARE FILE INFORMATION	2
SUPPORTED HARDWARE	2
BUG FIX	2
FIRMWARE VERSION 1.0.1.15	3
PRODUCT NAME	3
DATE	3
FIRMWARE FILE INFORMATION	3
SUPPORTED HARDWARE	3
BUG FIX	3
FIRMWARE VERSION 1.0.1.13	4
PRODUCT NAME	4
DATE	4
FIRMWARE FILE INFORMATION	4
SUPPORTED HARDWARE	4

FIRMWARE VERSION 1.0.1.16

PRODUCT NAME

DP755

DATE

11/21/2023

FIRMWARE FILE INFORMATION

- Firmware file name: **dp755fw.bin**
MD5: 0f3d7b373037441a8d772970ab0c0bdb
(Base station: Boot 1.0.1.16; Core 1.0.1.16; Prog 1.0.1.16; CPE 1.0.4.75
Handset: 1.0.19.16)

SUPPORTED HARDWARE

Base station:

- DP755 HW 1.0; 1.1

Handsets:

- DP730 HW 1.0; 1.1; 1.2
- DP722 HW 1.0; 1.1
- DP720 HW 1.0; 1.1; 1.2; 1.3; 1.4; 1.5; 1.6; 1.7; 1.8; 1.9; 2.0

Relay:

- DP760 HW 1.0; 1.1; 1.2; 1.3

NOTE:

- DP755 supports 10 handsets registration and 16 simultaneous calls on 8 handsets.
- DP755 DOES NOT include DP760 firmware, but it can work with DP760 to extend range.
- Handset firmware can NOT downgrade to 1.0.19.15 or below.

BUG FIX

- Fixed DP755 provision issue using HTTP DIGEST method.

FIRMWARE VERSION 1.0.1.15

PRODUCT NAME

DP755

DATE

10/16/2023

FIRMWARE FILE INFORMATION

- Firmware file name: **dp755fw.bin**
MD5: 7452c1f403cff911b515012179da647c
(Base station: Boot 1.0.1.15; Core 1.0.1.15; Prog 1.0.1.15; CPE 1.0.4.75
Handset: 1.0.19.16)

SUPPORTED HARDWARE

Base station:

- DP755 HW 1.0; 1.1

Handsets:

- DP730 HW 1.0; 1.1; 1.2
- DP722 HW 1.0; 1.1
- DP720 HW 1.0; 1.1; 1.2; 1.3; 1.4; 1.5; 1.6; 1.7; 1.8; 1.9; 2.0

Relay:

- DP760 HW 1.0; 1.1; 1.2; 1.3

NOTE:

- DP755 supports 10 handsets registration and 16 simultaneous calls on 8 handsets.
- DP755 DOES NOT include DP760 firmware, but it can work with DP760 to extend range.
- Handset firmware can NOT downgrade to 1.0.19.15 or below.

BUG FIX

- Fixed issues when using Metaswitch platform
- Internal bug fixes

FIRMWARE VERSION 1.0.1.13

PRODUCT NAME

DP755

DATE

09/25/2023

FIRMWARE FILE INFORMATION

- Firmware file name: **dp755fw.bin**
MD5: 84381f13876b84b67c6678781e80d897
(Base station: Boot 1.0.1.13; Core 1.0.1.13; Prog 1.0.1.13; CPE 1.0.4.72
Handset: 1.0.19.15)
- **This is the initial firmware for DP755.**

SUPPORTED HARDWARE

Base station:

- *DP755 HW 1.0; 1.1*

Handsets:

- *DP730 HW 1.0; 1.1; 1.2*
- *DP722 HW 1.0; 1.1*
- *DP720 HW 1.0; 1.1; 1.2; 1.3; 1.4; 1.5; 1.6; 1.7; 1.8; 1.9; 2.0*

Relay:

- *DP760 HW 1.0; 1.1; 1.2; 1.3*

NOTE:

- DP755 supports 10 handsets registration and 16 simultaneous calls on 8 handsets.
- DP755 DOES NOT include DP760 firmware, but it can work with DP760 to extend range.

For detailed information about DP755, please refer to User Manual and Resource Center:

<https://documentation.grandstream.com/article-categories/dect-base-stations/>