

# GSC3505/GSC3510 Firmware Release Notes

## Table of Content

<b>FIRMWARE VERSION 1.0.1.10.....</b>	<b>3</b>
PRODUCT NAME.....	3
DATE.....	3
FIRMWARE FILE INFORMATION.....	3
CHANGES SINCE FIRMWARE VERSION 1.0.1.9.....	3
BUG FIX.....	3
<b>FIRMWARE VERSION 1.0.1.9.....</b>	<b>4</b>
PRODUCT NAME.....	4
DATE.....	4
FIRMWARE FILE INFORMATION.....	4
CHANGES SINCE FIRMWARE VERSION 1.0.1.6.....	4
BUG FIX.....	4
<b>FIRMWARE VERSION 1.0.1.6.....</b>	<b>5</b>
PRODUCT NAME.....	5
DATE.....	5
FIRMWARE FILE INFORMATION.....	5
CHANGES SINCE FIRMWARE VERSION 1.0.1.5.....	5
ENHANCEMENT.....	5
BUG FIX.....	5
<b>FIRMWARE VERSION 1.0.1.5.....</b>	<b>6</b>
PRODUCT NAME.....	6
DATE.....	6
FIRMWARE FILE INFORMATION.....	6
CHANGES SINCE FIRMWARE VERSION 1.0.1.3.....	6
ENHANCEMENT.....	6
BUG FIX.....	6
NEW FEATURES OVERVIEW.....	6
INCOMING CALL RULES FOR EACH ACCOUNT.....	6
<b>FIRMWARE VERSION 1.0.1.3.....</b>	<b>8</b>
PRODUCT NAME.....	8
DATE.....	8
FIRMWARE FILE INFORMATION.....	8
CHANGES SINCE FIRMWARE VERSION 1.0.1.1.....	8
ENHANCEMENT.....	8
BUG FIX.....	8
NEW FEATURES OVERVIEW.....	8
REGISTER BEFORE DNS SRV FAIL-OVER.....	8
AUTOMATIC ANSWER RINGING TIME.....	9
BUSY TONE EXPIRATION.....	10
BLUETOOTH VISIBILITY TIMEOUT.....	10
ENABLE/DISABLE HTTP ACCESS.....	11
ENABLE/DISABLE DNS SERVER QUERY.....	12
AUTO MODE PLAY TIME.....	12
<b>FIRMWARE VERSION 1.0.1.1.....</b>	<b>14</b>
PRODUCT NAME.....	14
DATE.....	14
FIRMWARE FILE INFORMATION.....	14
CHANGES SINCE FIRMWARE VERSION 1.0.0.24.....	14

<i>ENHANCEMENT</i> .....	14
<i>BUG FIX</i> .....	14
NEW FEATURES OVERVIEW .....	15
<i>MUSIC/RADIO STREAMING</i> .....	15
<i>BLUETOOTH PIN CODE</i> .....	15
<i>MIN/MAX TLS VERSION</i> .....	16

## **FIRMWARE VERSION 1.0.1.10**

### **PRODUCT NAME**

GSC3505/GSC3510

### **DATE**

10/21/20

### **FIRMWARE FILE INFORMATION**

- Firmware file name: gsc3505fw.bin
- Firmware file name: gsc3510fw.bin

MD5: 2da54332d952383b5c8e6289807999e8

### **CHANGES SINCE FIRMWARE VERSION 1.0.1.9**

#### **BUG FIX**

- Fixed issue where GSC3505/GSC3510 wouldn't stay connected to GDMS after being factory reset via CPE.

## FIRMWARE VERSION 1.0.1.9

### PRODUCT NAME

GSC3505/GSC3510

### DATE

07/23/20

### FIRMWARE FILE INFORMATION

- Firmware file name: gsc3505fw.bin
- Firmware file name: gsc3510fw.bin

MD5: 438ec80d1e9ef473244e98b34d1a90da

### CHANGES SINCE FIRMWARE VERSION 1.0.1.6

#### BUG FIX

- Fixed issue where you can use the serial port to change the local RTP port to outside the allowed range
- Fixed issue where bluetooth could not be turned off through provisioning
- Fixed issue where if you use mDNS, the packet shows up as PTR regardless if you select Type SRV or Type A for \_grandstream-cfg query
- Fixed v2 config not provisioning issues

## FIRMWARE VERSION 1.0.1.6

### PRODUCT NAME

GSC3505/GSC3510

### DATE

05/08/20

### FIRMWARE FILE INFORMATION

- Firmware file name: gsc3505fw.bin
- Firmware file name: gsc3510fw.bin

MD5: 4931d45d0693c4c290d819bddd4995c

### CHANGES SINCE FIRMWARE VERSION 1.0.1.5

#### ENHANCEMENT

- Added the ability to generate a zip file for multiple recording files
- Added the missed calls notification on Web UI
- Optimized web UI tooltips
- Optimized the sensor functions of the device

#### BUG FIX

- Fixed audio issue during multicast/paging
- Fixed the whitelist/blacklist provisioning issue
- Fixed Broadsoft INVITE and BYE failover issue

## FIRMWARE VERSION 1.0.1.5

### PRODUCT NAME

GSC3505/GSC3510

### DATE

01/20/20

### FIRMWARE FILE INFORMATION

- Firmware file name: gsc3505fw.bin
- Firmware file name: gsc3510fw.bin

MD5: b7df8ddb9a5e9afbd772bb3e3d235a9e

### CHANGES SINCE FIRMWARE VERSION 1.0.1.3

#### ENHANCEMENT

- Added the incoming rules options for each account [INCOMING CALL RULES FOR EACH ACCOUNT]
- Added Call Settings and Ringtone Settings for each account on GSC3505
- Added the error message for WPA/WPA2 password requirement
- Optimized the audio quality and improving the duplex algorithm
- Optimized some P-values that are not working on previous firmware

#### BUG FIX


- Fixed ring back tone issue when there is a password set for an incoming call
- Fixed P-value for provisioning blacklist and whitelist through Web UI
- Fixed the abnormality of the call waiting behavior
- Fixed some call waiting and call waiting tone issue
- Fixed LED status lights issue
- Fixed some Portuguese incorrect translation

### NEW FEATURES OVERVIEW

This section lists major new features and describes how to use it from the user's point of view.

#### INCOMING CALL RULES FOR EACH ACCOUNT

- **Web Configuration**  
This option can be found on the web UI under Account -> Account# -> Call Settings -> Incoming Call Rules.



- Functionality**  
 Allow to set incoming call rules for each account registered. This configuration will over rule the global incoming call rules.
- P-Value**

P-Value	Description	Value Range	Default
P60044	Incoming Call Rules	0, 1, 2, 3, 4	4
P60045	Incoming Call Rules – Password	Numbers Only	

## FIRMWARE VERSION 1.0.1.3

### PRODUCT NAME

GSC3505/GSC3510

### DATE

01/02/20

### FIRMWARE FILE INFORMATION

- Firmware file name: gsc3505fw.bin
- Firmware file name: gsc3510fw.bin

MD5: 3844a6e1e043e61e87ae492a7766ecfa

### CHANGES SINCE FIRMWARE VERSION 1.0.1.1

#### ENHANCEMENT

- Added to support failover mechanism based on DNS SRV [REGISTER BEFORE DNS SRV FAIL-OVER]
- Added the ability to delay the auto-answer [AUTOMATIC ANSWER RINGING TIME]
- Added the ability to adjust the Busy Tone Expiration [BUSY TONE EXPIRATION]
- Added a timeout when the Visible to nearby Bluetooth devices is on [BLUETOOTH VISIBILITY TIMEOUT]
- Added the option to Enable/Disable the HTTP access [ENABLE/DISABLE HTTP ACCESS]
- Added the ability to disable IP2location and Wifi Certification [ENABLE/DISABLE DNS SERVER QUERY]
- Added the ability to play/stream the music based on set schedule [AUTO MODE PLAY TIME]
- Added the ability to display date/time on the Web UI
- Added the ability to provision the audio level settings
- Added the ability to support MP3 Format files on the Music Feature
- Optimized some P-values that are not working on previous firmware

#### BUG FIX

- Fixed some call history issue that won't show after awhile
- Fixed Bluetooth PIN mismatching when pairing with GXP
- Fixed the Bluetooth Codec negotiation to support broadband (mSBC)
- Fixed the IPv6 issue when only enabling IPv4 only
- Fixed incorrect Time zone for "São Paulo" to UTC-3
- Fixed hold the SIP call when there is an incoming call from connected Bluetooth devices
- Fixed RTSP stream will not resume after receiving a call
- Fixed RTSP address cannot be saved when it's not in the correct format
- Fixed Dropping a call when there is a second incoming call
- Fixed the TR069 settings when configured
- Fixed Bluetooth lost connection with GVC after rebooting the GVC
- Fixed some Bluetooth configuration issue after reboot

### NEW FEATURES OVERVIEW


This section lists major new features and describes how to use it from the user's point of view.

#### REGISTER BEFORE DNS SRV FAIL-OVER

- **Web Configuration**



This option can be found on the web UI under Account -> Account# -> General Settings -> Register Before DNS SRV Fail-Over.




- Functionality**  
 When this feature is enabled, the device will register using the outbound proxy when the SIP server is failed to get the registration.
- P-Value**

P-Value	Description	Value Range	Default
P29095, P29195, P29295, P29395, P29495, P29595, P53695, P53795, P53895, P53995, P54095, P54195, P54295, P54395, P54495, P54595	Register Before DNS SRV Fail-over for each account#	0, 1	1

#### AUTOMATIC ANSWER RINGING TIME

- Web Configuration**  
 This option can be found on the web UI under Phone Settings -> Call Settings -> Automatic Answer Ringing Time.




- **Functionality**  
Allow the GSC to ringing for some specific time (in seconds) before auto-answering the incoming call when the Greylist set to Auto-Answer.
- **P-Value**

P-Value	Description	Value Range	Default
P8486	Automatic answer ringing time	0 – 60 (seconds)	5

#### BUSY TONE EXPIRATION

- **Web Configuration**  
This option can be found on the web UI under Phone Settings -> Call Settings -> Busy Tone Ring Time (s).




- **Functionality**  
Configure the timeout for Busy Tone during the call.
- **P-Value**

P-Value	Description	Value Range	Default
P8347	Busy Tone Ring Time (s)	0 – 120	30

#### BLUETOOTH VISIBILITY TIMEOUT

- **Web Configuration**  
This option can be found on the web UI under Network Settings -> Bluetooth -> Visibility Timeout.




- Functionality**  
 GSC3505/GSC3510 added some options for Bluetooth Visibility timeout before the it turned back to 'Invisible' mode.
- P-Value**

P-Value	Description	Value Range	Default
P22331	Bluetooth Visibility Timeout	0, 2, 5, 60	2

#### ENABLE/DISABLE HTTP ACCESS

- Web Configuration**  
 This option can be found on the web UI under System Settings -> Security Settings -> Web/SSH Access -> Allow Web Page Access.



- Functionality**  
 Enable/disable the HTTP Access.


- **P-Value**

P-Value	Description	Value Range	Default
P29605	Allow Web Page Access	0, 1	1

#### ENABLE/DISABLE DNS SERVER QUERY

- **Web Configuration**

This option can be found on the web UI under Maintenance -> Upgrade -> Advanced Settings -> Allow AutoConfig service access.



- **Functionality**

Options to enable/disable to access the AutoConfig service from service.ipvideotalk.com


- **P-Value**

P-Value	Description	Value Range	Default
P7070	Allow AutoConfig Service Access	0, 1	1

#### AUTO MODE PLAY TIME

- **Web Configuration**

This option can be found on the web UI under Applications -> Music -> Auto Mode Play Time.



- Functionality**  
 To set some schedule to play/stream the music during Auto Mode.

## FIRMWARE VERSION 1.0.1.1

### PRODUCT NAME

GSC3505/GSC3510

### DATE

9/24/19

### FIRMWARE FILE INFORMATION

- Firmware file name: gsc3505fw.bin
- Firmware file name: gsc3510fw.bin

MD5: 91a540eb5b2777c810d9bf06536e66fa

### CHANGES SINCE FIRMWARE VERSION 1.0.0.24

#### ENHANCEMENT

- Added the ability to stream Radio/Music on the device. [MUSIC/RADIO STREAMING]
- Added pairing PIN code with Bluetooth device. [BLUETOOTH PIN CODE]
- Added minimum & maximum TLS version. [MIN/MAX TLS VERSION]
- Added a prompt to restart the device after modifying PNP (3CX) Auto Provision
- Added an ability to adjust the volume during playing the radio/music
- Changing "DATE" for the time display under call history and recording files to "TIME AND DATE"
- Optimized web UI prompts
- Optimized the audio quality

#### BUG FIX

- Fixed the calling prompt after ended the call from GVC when connecting using Bluetooth
- Fixed the inconsistency the volume during an active call
- Fixed the duplication issue when adding the numbers to the whitelist/blacklist
- Fixed adding a contact from the call history if the contact already existed in contact list
- Fixed call history does not refresh automatically
- Fixed unable to save the audio file address when editing both audio file address and play mode
- Fixed non-stop playing music when modifying the audio file address during the playback
- Fixed some DHCP issues after rebooting the device
- Fixed failing automatically downloads contacts after download interval
- Fixed failing to get a network address when using PPPoE
- Fixed some error when displaying the time on recording file
- Fixed the password input name shown as SSID in MAC&PEM
- Fixed the display name when the detected Bluetooth devices is using Chinese characters
- Fixed not displaying the second incoming call interface
- Fixed abnormality when unplugging/plugging the internet cable or switching networks
- Fixed some DTMF issue during call
- Fixed unable to delete a contact after 2000 contacts
- Fixed successfully saved the configuration when the IP, subnet mask, and default gateway are empty on when using Static IP


## NEW FEATURES OVERVIEW

This section lists major new features and describes how to use it from the user's point of view.

### MUSIC/RADIO STREAMING

- **Web Configuration**

This option can be found on the web UI under Applications -> Music.



- **Functionality**

Allow to stream a radio using RTSP address, for example: rtsp://ip address/musicFile.ts. Also, allow to play an audio file that is in RTSP format (.ts) or a RTSP format file converted from MP3 format.


- **P-Value**

P-Value	Description	Value Range	Default
P953	RTSP Server Path	See Config template for full value list	
P22328	RTSP Play Mode		0

### BLUETOOTH PIN CODE

- **Web Configuration**

This option can be found on the web UI under Network Settings -> Bluetooth -> Bluetooth PIN



- **Functionality**

GSC3505/GSC3510 added support a PIN Code when connecting with Bluetooth devices.

- **P-Value**


P-Value	Description	Value Range	Default
P22291	Bluetooth Pair Pin Code	Numbers only	

#### MIN/MAX TLS VERSION

- **Web Configuration**

This option can be found on the web UI under System Settings -> Security Settings -> TLS -> Minimum TLS Version / Maximum TLS Version.





- **Functionality**

Allow the GSC3505/GSC3510 to accepting the connection from the lower TLS version.

- **P-Value**

P-Value	Description	Value Range	Default
P22293	Minimum TLS Version	See Config template for full value list	11
P22294	Maximum TLS Version		99