

GSC3505/GSC3510 Firmware Release Notes

Table of Content

FIRMWARE VERSION 1.0.1.1	2
PRODUCT NAME	2
DATE	2
FIRMWARE FILE INFORMATION	2
CHANGES SINCE FIRMWARE VERSION 1.0.0.24	2
<i>ENHANCEMENT</i>	2
<i>BUG FIX</i>	2
NEW FEATURES OVERVIEW.....	3
<i>MUSIC/RADIO STREAMING</i>	3
<i>BLUETOOTH PIN CODE</i>	3
<i>MIN/MAX TLS VERSION</i>	4

FIRMWARE VERSION 1.0.1.1

PRODUCT NAME

GSC3505/GSC3510

DATE

9/24/19

FIRMWARE FILE INFORMATION

- Firmware file name:
For GSC3505: gsc3505fw.bin
For GSC3510: gsc3510fw.bin
- MD5: 91a540eb5b2777c810d9bf06536e66fa

CHANGES SINCE FIRMWARE VERSION 1.0.0.24

ENHANCEMENT

- Added the ability to stream Radio/Music on the device. [MUSIC/RADIO STREAMING]
- Added pairing PIN code with Bluetooth device. [BLUETOOTH PIN CODE]
- Added minimum & maximum TLS version. [MIN/MAX TLS VERSION]
- Added a prompt to restart the device after modifying PNP (3CX) Auto Provision
- Added an ability to adjust the volume during playing the radio/music
- Changed "DATE" for the time display under call history and recording files to "TIME AND DATE"
- Optimized web UI prompts
- Optimized the audio quality

BUG FIX

- Fixed the calling prompt after ended the call from GVC when connecting using Bluetooth
- Fixed the inconsistency the volume during an active call
- Fixed the duplication issue when adding the numbers to the whitelist/blacklist
- Fixed adding a contact from the call history if the contact already existed in contact list
- Fixed call history does not refresh automatically
- Fixed unable to save the audio file address when editing both audio file address and play mode
- Fixed non-stop playing music when modifying the audio file address during the playback
- Fixed some DHCP issues after rebooting the device
- Fixed failing automatically downloads contacts after download interval
- Fixed failing to get a network address when using PPPoE
- Fixed some error when displaying the time on recording file
- Fixed the password input name shown as SSID in MAC&PEM

- Fixed the display name when the detected Bluetooth devices is using Chinese characters
- Fixed not displaying the second incoming call interface
- Fixed abnormality when unplugging/plugging the internet cable or switching networks
- Fixed some DTMF issue during call
- Fixed unable to delete a contact after 2000 contacts
- Fixed successfully saved the configuration when the IP, subnet mask, and default gateway are empty on when using Static IP


NEW FEATURES OVERVIEW

This section lists major new features and describes how to use it from the user's point of view.

MUSIC/RADIO STREAMING

- **Web Configuration**

This option can be found on the web UI under Applications -> Music.




- **Functionality**

Allow to stream a radio using RTSP address, for example: rtsp://ip address/musicFile.ts. Also, allow to play an audio file that is in RTSP format (.ts) or a RTSP format file converted from MP3 format.

BLUETOOTH PIN CODE

- **Web Configuration**

This option can be found on the web UI under Network Settings -> Bluetooth -> Bluetooth PIN



- **Functionality**

GSC3505/GSC3510 added support a PIN Code when connecting with Bluetooth devices. It requires to have 6 digits of PIN Code.


- **P-Value**

P-Value	Description	Value Range	Default
P22291	Bluetooth Pair Pin Code	Numbers only	

MIN/MAX TLS VERSION

- **Web Configuration**

This option can be found on the web UI under System Settings -> Security Settings -> TLS -> Minimum TLS Version / Maximum TLS Version.



- **Functionality**

Allow the GSC3505/GSC3510 to accepting the connection from the lower TLS version.

- **P-Value**

P-Value	Description	Value Range	Default
P22293	Minimum TLS Version	See Config template for full value list	11
P22294	Maximum TLS Version		99