

GWN7610 Firmware Release Note

IMPORTANT UPGRADING NOTE

- A factory reset is required after upgrading from 1.0.1.x firmware to 1.0.2.x, in order to adopt the new factory parameters of data collection feature for supporting new overview page.

Table of Content

IMPORTANT UPGRADING NOTE	1
FIRMWARE VERSION 1.0.2.15	3
PRODUCT NAME.....	3
DATE	3
IMPORTANT UPGRADING NOTE	3
ENHANCEMENT	3
BUG FIX	3
KNOWN ISSUE	3
FIRMWARE VERSION 1.0.1.27	4
PRODUCT NAME.....	4
DATE	4
IMPORTANT UPGRADING NOTE	4
ENHANCEMENT	4
BUG FIX	4
KNOWN ISSUE	4

FIRMWARE VERSION 1.0.2.15

PRODUCT NAME

GWN7610

DATE

1/31/2017

IMPORTANT UPGRADING NOTE

You will need a factory reset after upgrading from 1.0.1.x firmware, in order to adopt the new factory parameters of data collection feature for supporting new overview page.

ENHANCEMENT

- New Overview Page.
- WebUI enhancement.
- Enforcing password change on first login. User will need to modified the default login password “admin” on the first login.
- Country code selection is added into setup wizard.

BUG FIX

- Internal bug fixes.

KNOWN ISSUE

- SNMP does not work in this version.
- Banned Band steering feature still affect wireless Black/White/Banned client list feature. Please use Band steering or Black/White/Banned client list feature exclusively.

FIRMWARE VERSION 1.0.1.27

PRODUCT NAME

GWN7610

DATE

11/15/2016

IMPORTANT UPGRADING NOTE

This is the initial release of GWN7610.

ENHANCEMENT

BUG FIX

KNOWN ISSUE

- Banned Band steering feature will affect wireless Black/White/Banned client list feature. Please use Band steering or Black/White/Banned client list feature exclusively.
- 'Landing Page' feature is not enabled.