

# GXW450X Firmware Release Notes

## Table of Content

<b>FIRMWARE VERSION 1.0.0.24</b> .....	<b>1</b>
PRODUCT NAME.....	1
DATE .....	1
FIRMWARE FILE INFORMATION .....	1
CHANGES/ENHANCEMENT .....	1
<b>FIRMWARE VERSION 1.0.0.22</b> .....	<b>2</b>
PRODUCT NAME.....	2
DATE .....	2
FIRMWARE FILE INFORMATION .....	2
CHANGES/ENHANCEMENT .....	2
KNOWN ISSUE .....	2
<b>FIRMWARE VERSION 1.0.0.20</b> .....	<b>3</b>
PRODUCT NAME.....	3
DATE .....	3
FIRMWARE FILE INFORMATION .....	3
CHANGES/ENHANCEMENT .....	3
KNOWN ISSUE .....	3
<b>FIRMWARE VERSION 1.0.0.18</b> .....	<b>4</b>
PRODUCT NAME.....	4
DATE .....	4
FIRMWARE FILE INFORMATION .....	4
IMPORTANT UPGRADING NOTE .....	4
KNOWN ISSUE .....	4

## **FIRMWARE VERSION 1.0.0.24**

### **PRODUCT NAME**

GXW4501/GXW4502/GXW4504

### **DATE**

06/06/2019

### **FIRMWARE FILE INFORMATION**

- GXW450X firmware file name: gxw4500fw.bin

MD5 checksum: c1319547317e5571b12a79e497c97e02

### **CHANGES/ENHANCEMENT**

- Internal bug fixes

## FIRMWARE VERSION 1.0.0.22

### PRODUCT NAME

GXW4501/GXW4502/GXW4504

### DATE

04/26/2019

### FIRMWARE FILE INFORMATION

- GXW450X firmware file name: gxw4500fw.bin

MD5 checksum: 8988e06dd7730439d1a0623438e5dc45

### CHANGES/ENHANCEMENT

- Fixed issue that E1 option "PRI Indication" can't take effect
- Fixed issue that enabled static route may turn to disabled in few circumstances, including upgrading firmware, changing router/switch mode, or rebooting unit.
- Internal bug fixes

### KNOWN ISSUE

- Static IPv6 configuration page has no default gateway option. Need to manually add static route with destination ::/0 as default route.

## FIRMWARE VERSION 1.0.0.20

### PRODUCT NAME

GXW4501/GXW4502/GXW4504

### DATE

04/04/2019

### FIRMWARE FILE INFORMATION

- GXW450X firmware file name: gxw4500fw.bin

MD5 checksum: 46b423b21550e9043bbc042026618669

### CHANGES/ENHANCEMENT

- Fixed issue that Dynamic IPv6 WAN mode will need manually adding default gateway into static route. Now Dynamic IPv6 on WAN should work without need of manual configuration of static route.
- Fixed issue that importing inbound report csv file will fail if no existing inbound route configured.
- Fixed issue that Router model with PPPoE WAN setting will cause LAN device fail to connect internet.
- Internal bug fixes

### KNOWN ISSUE

- Static IPv6 configuration page has no default gateway option. Need to manually add static route with destination ::/0 as default route.
- Enabled static route may turn to disabled in few circumstances, including upgrading firmware, changing router/switch mode, or rebooting unit. However, the static route still functioning as enabled, and reboot will fix the display issue.
- E1 option "PRI Indication" can't take effect

## **FIRMWARE VERSION 1.0.0.18**

### **PRODUCT NAME**

GXW4501/GXW4502/GXW4504

### **DATE**

03/22/2019

### **FIRMWARE FILE INFORMATION**

- GXW450X firmware file name: gxw4500fw.bin
- MD5 checksum: f62de1499dbec183cd779a052f321459

### **IMPORTANT UPGRADING NOTE**

- This is first release of GXW450X

### **KNOWN ISSUE**

- Router model with PPPoE WAN setting will cause LAN device fail to connect internet.
- After upgrade from older firmware version to 1.0.0.18. Enabled static route may turn to disabled. However, it's still functioning as enabled. Reboot will fix the display issue.
- Import inbound report csv file will fail if no existing inbound route configured. Manually add one inbound route will fix the issue.
- Dynamic IPv6 WAN mode will need manually adding default gateway into static route.