

GWN7062E/ET Router Firmware Release Notes

Table of Content

FIRMWARE FILE DOWNLOAD	3
FIRMWARE VERSION 1.0.3.23	4
PRODUCT NAME	4
DATE	4
FIRMWARE FILE INFORMATION	4
CHANGES/ENHANCEMENT	4
FIRMWARE VERSION 1.0.3.10	5
PRODUCT NAME	5
DATE	5
FIRMWARE FILE INFORMATION	5
CHANGES/ENHANCEMENT	5
FIRMWARE VERSION 1.0.3.7	6
PRODUCT NAME	6
DATE	6
FIRMWARE FILE INFORMATION	6
CHANGES/ENHANCEMENT	6
FIRMWARE VERSION 1.0.1.13	8
PRODUCT NAME	8
DATE	8
FIRMWARE FILE INFORMATION	8
CHANGES/ENHANCEMENT	8
FIRMWARE VERSION 1.0.1.10	9
PRODUCT NAME	9
DATE	9
FIRMWARE FILE INFORMATION	9

CHANGES/ENHANCEMENT.....	9
FIRMWARE VERSION 1.0.1.7	10
PRODUCT NAME	10
DATE	10
FIRMWARE FILE INFORMATION	10
CHANGES/ENHANCEMENT.....	10

FIRMWARE FILE DOWNLOAD

Individual firmware files are available for downloading at URL below:

<https://www.grandstream.com/support/firmware>

FIRMWARE VERSION 1.0.3.23

PRODUCT NAME

GWN7062E / GWN7062ET

DATE

1/5/2026

FIRMWARE FILE INFORMATION

- GWN7062E Firmware file name: gwn7062efw.bin
MD5 checksum: 151ee3f5f0069b1fedd634c270f0784f
- GWN7062ET Firmware file name: gwn7062etfw.bin
MD5 checksum: 75453368448b11bafd8d7bcad9f08075

CHANGES/ENHANCEMENT

- Added the ability to configure FXS when GWN7062ET is MESH RE.
- Added the ability to provision device via HTTP.
- Added the ability to disable the default SSID.
- Added WAN Speed Test feature on GDMS.
- Fixed an issue where the manual channel assignment does not take effect on the GWN7062ET.
- Fixed an issue where Device lost IPSEC VPN config after reboot.
- Fixed an issue when ICMP is blocked, the router Internet Status indicator shows “No Internet”.
- Fixed an issue where exported OpenVPN file cannot be loaded on OpenVPN Connect due to “rport” is not supported by the latest version.
- Disabled UNII-4 channels (including 169, 173 and 177) by default.
- Internal bug fixes.

FIRMWARE VERSION 1.0.3.10

PRODUCT NAME

GWN7062E / GWN7062ET

DATE

9/30/2025

FIRMWARE FILE INFORMATION

- GWN7062E Firmware file name: gwn7062efw.bin
MD5 checksum: 8b28795c668981cf3c7a030f70eb0af3
- GWN7062ET Firmware file name: gwn7062etfw.bin
MD5 checksum: f2c1cd0fffdac941fc3b135de442499c

CHANGES/ENHANCEMENT

- Fixed the issue where the TR069 ACS URL address was cleared after device restart.
- Internal bug fixes.

FIRMWARE VERSION 1.0.3.7

PRODUCT NAME

GWN7062E / GWN7062ET

DATE

6/26/2025

FIRMWARE FILE INFORMATION

- GWN7062E Firmware file name: gwn7062efw.bin
MD5 checksum: 728d79ddd45283f7bb8822f219f1a769
- GWN7062ET Firmware file name: gwn7062etfw.bin
MD5 checksum: f2a68cae4e0e026bdac1aede150003c

CHANGES/ENHANCEMENT

- Added support for [Grandstream Home app](#) which allows users to setup, control, and monitor home networks from mobile phones.
- Added support for Wireless Relay Mode and Wireless Bridge Mode under “System” -> “Working Mode”.
- Updated the entire Mesh addition process. Mesh is separated from Wi-Fi settings now.
- Added support for SafeSearch function for HomeCare.
- Changed button name and function from “Block” to “Block internet”, and “Allow” to “Add time” under HomeCare -> Parental Control page.
- Changed “Cloud” to “Management Platform”.
- Added “Grandstream Home” page under “Management Platform” page.
- Added Security Version to System Info page.
- Added a text hint under WAN settings when the WAN is enabled: “To configure VLAN, go to [Internet settings-ISP] and select corresponding working mode”.
- Changed menu “Triple Play” to “ISP” to avoid confusion.

- Added support for “IP Address Direct Dialing” to the “Telephony” -> “Basic Settings” page.
- Deleted the “Outgoing Call Without Registration” from “FXS Settings” page.
- Added support for “Guest Wi-Fi” under Wi-Fi Settings:
- Changed Wi-Fi “General settings” location and added more items.
- IPv6 function and configuration page restructured.
- Internal bug fixes.

FIRMWARE VERSION 1.0.1.13

PRODUCT NAME

GWN7062E / GWN7062ET

DATE

5/21/2025

FIRMWARE FILE INFORMATION

- GWN7062E Firmware file name: gwn7062efw.bin
MD5 checksum: aa0a70ac0b570d05fd5497ee37d6ee11
- GWN7062ET Firmware file name: gwn7062etfw.bin
MD5 checksum: dfb70b47a05f98fdb88831ff5b940da3

CHANGES/ENHANCEMENT

- Added support for Wi-Fi 5 compatibility mode switch.
- Added support for Wi-Fi radio power configuration.
- Added support to config lock 802.1Q.
- Fixed some internal issues.

FIRMWARE VERSION 1.0.1.10

PRODUCT NAME

GWN7062E / GWN7062ET

DATE

5/7/2025

FIRMWARE FILE INFORMATION

- GWN7062E Firmware file name: gwn7062efw.bin
MD5 checksum: 36f258f28b4ae6301213f3757bb75ead
- GWN7062ET Firmware file name: gwn7062etfw.bin
MD5 checksum: e2de2f77e5ce08b373c44f566f7907ff

CHANGES/ENHANCEMENT

- Fixed issue that the SSID encryption method cannot be set to "Open".
- Fixed some internal issues.

FIRMWARE VERSION 1.0.1.7

PRODUCT NAME

GWN7062E / GWN7062ET

DATE

4/16/2025

FIRMWARE FILE INFORMATION

- GWN7062E Firmware file name: gwn7062efw.bin
MD5 checksum: 5f5b85284e98a8679da73b63b9028086
- GWN7062ET Firmware file name: gwn7062etfw.bin
MD5 checksum: be0345126a8bade60cbd453c48acc1c5

CHANGES/ENHANCEMENT

- This is the first release of GWN7062E and GWN7062ET.