

GCC601X UC + Networking Convergence Solutions

System Firmware Release Notes

IMPORTANT UPGRADING NOTE

- [7/26/2024] [1.0.1.32(SYS)] Changed the default value from Enable to Disable for “**Allow DHCP Option 43 and 66 to Override Server**” and “**Check/Download New Firmware at Bootup**”. Upon upgrading from older version, these two options will be disabled. Please re-enable it if needed.

Table of Content

| | |
|---|----------|
| IMPORTANT UPGRADING NOTE | 1 |
| FIRMWARE FILE DOWNLOAD | 3 |
| FIRMWARE VERSION 1.0.1.32(SYS) | 4 |
| PRODUCT NAME..... | 4 |
| DATE | 4 |
| FIRMWARE FILE INFORMATION | 4 |
| CHANGES/ENHANCEMENT | 4 |
| FIRMWARE VERSION 1.0.1.10(SYS) | 5 |
| PRODUCT NAME..... | 5 |
| DATE | 5 |
| FIRMWARE FILE INFORMATION | 5 |
| CHANGES/ENHANCEMENT | 5 |
| FIRMWARE VERSION 1.0.1.8(SYS)..... | 6 |
| PRODUCT NAME..... | 6 |
| DATE | 6 |
| FIRMWARE FILE INFORMATION | 6 |
| CHANGES/ENHANCEMENT | 6 |

FIRMWARE FILE DOWNLOAD

Individual firmware files are available for downloading at URL below:

<https://www.grandstream.com/support/firmware>

FIRMWARE VERSION 1.0.1.32(SYS)

PRODUCT NAME

GCC6010

DATE

7/26/2024

FIRMWARE FILE INFORMATION

- GCC6010 system firmware file name: gcc601xfw.bin
MD5 checksum: 3b6810c23b4ee941c534649ef84d41ea

CHANGES/ENHANCEMENT

- Resolved the Tiktok Live streaming issue when Antivirus is enabled.
- Changed the default value from Enable to Disable for “**Allow DHCP Option 43 and 66 to Override Server**” and “**Check/Download New Firmware at Bootup**”. Upon upgrade from older version, these two options will be disabled, please re-enable it if needed.
- Changed the default value from 10sec to 300sec for all **Flood Attack Defense** timeout settings.
- Changed the default action to **Drop** for WAN **Inbound Rules** under **Firewall Policy**.
- Updated the DPI library, latest library is not compatible with SYS version lower than 1.0.1.32.
- Updated the IPS, URL, and Antivirus signature library.
- Internal bug fixes.

FIRMWARE VERSION 1.0.1.10(SYS)

PRODUCT NAME

GCC6010

DATE

6/28/2024

FIRMWARE FILE INFORMATION

- GCC6010 system firmware file name: gcc601xfw.bin
MD5 checksum: c3b812966176a904282000ab622f3011

CHANGES/ENHANCEMENT

- Disable **Check/Download New Firmware at Bootup** by default.
- Internal bug fixes.

FIRMWARE VERSION 1.0.1.8(SYS)

PRODUCT NAME

GCC6010

DATE

6/4/2024

FIRMWARE FILE INFORMATION

- GCC6010 system firmware file name: gcc601xfw.bin
MD5 checksum: 0294ea7965254b2e99d10a5399bfd05b

CHANGES/ENHANCEMENT

- This is the initial release of GCC6010 system firmware.