

# GHP630/630W/631/631W Firmware Release Notes

## Table of Content

<b>FIRMWARE VERSION 1.0.1.41 .....</b>	<b>3</b>
PRODUCT NAME.....	3
DATE .....	3
FIRMWARE FILE INFORMATION .....	3
BUG FIX .....	3
<b>FIRMWARE VERSION 1.0.1.40 .....</b>	<b>4</b>
PRODUCT NAME.....	4
DATE .....	4
FIRMWARE FILE INFORMATION .....	4
ENHANCEMENT .....	4
BUG FIX .....	4
<b>FIRMWARE VERSION 1.0.1.28 .....</b>	<b>5</b>
PRODUCT NAME.....	5
DATE .....	5
FIRMWARE FILE INFORMATION .....	5
ENHANCEMENT .....	5
BUG FIX .....	5
NEW FEATURE OVERVIEW .....	5
<i>DISABLE MISSED CALL NOTIFICATION</i> .....	5
<b>FIRMWARE VERSION 1.0.1.26 .....</b>	<b>7</b>
PRODUCT NAME.....	7
DATE .....	7
FIRMWARE FILE INFORMATION .....	7
ENHANCEMENT .....	7
BUG FIX .....	7
NEW FEATURE OVERVIEW .....	7
<i>LCD CONFIGURATION VIA KEYPAD MENU</i> .....	7
<i>DATE DISPLAY FORMAT</i> .....	8
<i>SHOW CLOCK</i> .....	9
<b>FIRMWARE VERSION 1.0.1.24 .....</b>	<b>10</b>

PRODUCT NAME.....	10
DATE .....	10
FIRMWARE FILE INFORMATION .....	10
ENHANCEMENT .....	10
BUG FIX .....	10
<b>FIRMWARE VERSION 1.0.1.23 .....</b>	<b>11</b>
PRODUCT NAME.....	11
DATE .....	11
FIRMWARE FILE INFORMATION .....	11
ENHANCEMENT .....	11
<b>FIRMWARE VERSION 1.0.1.13 .....</b>	<b>12</b>
PRODUCT NAME.....	12
DATE .....	12
FIRMWARE FILE INFORMATION .....	12

## **FIRMWARE VERSION 1.0.1.41**

### **PRODUCT NAME**

GHP630, GHP630W, GHP631, GHP631W

### **DATE**

04/02/25

### **FIRMWARE FILE INFORMATION**

- Firmware file name: ghp630fw.bin  
MD5: f547c7556cae9aa6c6d4ee521c2bdd1c

### **BUG FIX**

- Fixed an issue where wallpaper could fail to download on bootup if it doesn't receive an internet connection fast enough
- Fixed an issue where the phone would dial out using the speakerphone instead of the off-hook handset when using softkeys to dial
- Fixed a security vulnerability

## FIRMWARE VERSION 1.0.1.40

### PRODUCT NAME

GHP630, GHP630W, GHP631, GHP631W

### DATE

02/12/25

### FIRMWARE FILE INFORMATION

- Firmware file name: ghp630fw.bin  
MD5: da57eb092eb1d68a592cba69ef5dc789

### ENHANCEMENT

- Added support for deleting call logs after guest checkout when using UCM

### BUG FIX

- Fixed an issue where if the admin password set after factory reset includes a “+” then you couldn’t log in using the new password
- Fixed an issue where you can have 1-way audio when using SRTP if the phone receives a re-INVITE that has the same codec but a different SRTP key
- Fixed a registration and call issue that could occur on fw 1.0.1.36 when using Special Feature: “BroadSoft” with SIP Transport: “TCP” or “TLS/TCP”

## FIRMWARE VERSION 1.0.1.28

### PRODUCT NAME

GHP630, GHP630W, GHP631, GHP631W

### DATE

10/30/2024

### FIRMWARE FILE INFORMATION

- Firmware file name: ghp630fw.bin  
MD5: 002280787c013482c6a312b92253bac4

### ENHANCEMENT

- Added ability to disable missed call and VM notifications[DISABLE MISSED CALL NOTIFICATION]

### BUG FIX


- Removed unnecessary voltage warning when using some third-party PSU
- Fixed an issue where when trying to access voicemail, the phone prompts you to select an account even though there is only one active account
- Fixed an issue where the phone would sometimes fail to download the wallpaper on bootup due to reaching the download retry limit before the network is ready
- Fixed an issue where auto-answer would continue to use the handset instead of the speaker even after the handset is put back on-hook
- Fixed a security vulnerability

### NEW FEATURE OVERVIEW

#### DISABLE MISSED CALL NOTIFICATION

##### Web Configuration

This option can be found under device web UI→Phone Settings→Call Settings.

Enable Missed Call Notification 



**Functionality**

Configures whether to enable the missed call and voicemail notifications.

**Pvalue**

Pvalue	Description	Value Range	Default
8393	<New Pvalue> Enable Missed Call Notification	0-1 0 – No 1 - Yes	1

## FIRMWARE VERSION 1.0.1.26

### PRODUCT NAME

GHP630, GHP630W, GHP631, GHP631W

### DATE

08/12/2024

### FIRMWARE FILE INFORMATION

- Firmware file name: ghp630fw.bin  
MD5: b98a5ea664d85db306e536e1d95159a0

### ENHANCEMENT

- Added support for access control of settings accessible via LCD[CONFIGURATION VIA KEYPAD MENU]
- Added support to change the Date Display Format[DATE DISPLAY FORMAT]
- Added support for disabling the center clock while the screen is active[SHOW CLOCK]

### BUG FIX

- Fixed an issue where when you try to change the VMPK icon via pvalue provisioning, the change is displayed on the Web UI but not on the LCD
- Fixed an issue where the device may display a voltage error message inaccurately
- Fixed an issue where the device wouldn't connect to the Wi-Fi network after provisioning the parameters via config file
- Fixed a security issue

### NEW FEATURE OVERVIEW


#### LCD CONFIGURATION VIA KEYPAD MENU

##### Web Configuration

This option can be found under device web UI→System Settings→Security Settings→Web/SSH Access.

Keypad Mode

Configuration via Keypad Menu 

Unrestricted 

### Functionality

Configures access control for keypad menu settings.

### Pvalue


Pvalue	Description	Value Range	Default
1357	<New Pvalue> Configuration via Keypad Menu	0-3 0 – Unrestricted 1 – Basic Settings Only 2 – Constraint Mode 3 – Locked Mode	0

## DATE DISPLAY FORMAT

### Web Configuration

This option can be found under device web UI→System Settings→Time and Language.

Date Display Format 

yyyy-mm-dd 

### Functionality

Configures the date display format on the LCD.

### Pvalue

Pvalue	Description	Value Range	Default
102	<New Pvalue> Configuration via Keypad Menu	0-4 0 – yyyy-mm-dd 1 – mm-dd-yyyy 2 – dd-mm-yyyy 3 – dddd, MMMM dd 4 – MMMM dd, dddd	0



## SHOW CLOCK

### Web Configuration

This option can be found under device web UI→System Settings→Time and Language.

Show Clock 

### Functionality

Configures whether to show or hide the clock on the idle screen.

### Pvalue

Pvalue	Description	Value Range	Default
8500	<New Pvalue> Show Clock	0-1 0 – No 1 - Yes	1

## FIRMWARE VERSION 1.0.1.24

### PRODUCT NAME

GHP630, GHP630W, GHP631, GHP631W

### DATE

05/17/2024

### FIRMWARE FILE INFORMATION

- Firmware file name: ghp630fw.bin  
MD5: f05581d87ae8b80b33730e107f3fda82

### ENHANCEMENT

- Increased “Off-hook Auto Dial Delay” max value from 10 to 30 seconds

### BUG FIX

- Fixed an issue where the account status of account 2 would be displayed incorrectly on GDMS if you configure two accounts simultaneously on GDMS
- Removed “Cal History Outgoing Call” option for the “Bypass Dial Plan” setting since call history isn’t supported on LCD yet
- Fixed an issue where the phone wouldn’t download wallpapers when using HTTPS

## **FIRMWARE VERSION 1.0.1.23**

### **PRODUCT NAME**

GHP630, GHP630W, GHP631, GHP631W

### **DATE**

04/17/2024

### **FIRMWARE FILE INFORMATION**

- Firmware file name: ghp630fw.bin  
MD5: c3301c1726bba1034e6b64ca52097c07

### **ENHANCEMENT**

- Phone now disables web access while in-call to help improve performance

## FIRMWARE VERSION 1.0.1.13

### PRODUCT NAME

GHP630, GHP630W, GHP631, GHP631W

### DATE

03/20/2024

### FIRMWARE FILE INFORMATION

- Firmware file name: ghp630fw.bin  
MD5: 257f3a5e5b2bb7d9dbaeacd3f4ec3a8b

This is the Initial firmware for GHP630/630W/631/631W.