

# GHP630/630W/631/631W Firmware Release Notes

## Table of Content

<b>FIRMWARE VERSION 1.0.1.24 .....</b>	<b>2</b>
PRODUCT NAME.....	2
DATE .....	2
FIRMWARE FILE INFORMATION .....	2
ENHANCEMENT .....	2
BUG FIX .....	2
<b>FIRMWARE VERSION 1.0.1.23 .....</b>	<b>3</b>
PRODUCT NAME.....	3
DATE .....	3
FIRMWARE FILE INFORMATION .....	3
ENHANCEMENT .....	3
<b>FIRMWARE VERSION 1.0.1.13 .....</b>	<b>4</b>
PRODUCT NAME.....	4
DATE .....	4
FIRMWARE FILE INFORMATION .....	4

## **FIRMWARE VERSION 1.0.1.24**

### **PRODUCT NAME**

GHP630, GHP630W, GHP631, GHP631W

### **DATE**

05/17/2024

### **FIRMWARE FILE INFORMATION**

- Firmware file name: ghp630fw.bin  
MD5: f05581d87ae8b80b33730e107f3fda82

### **ENHANCEMENT**

- Increased “Off-hook Auto Dial Delay” max value from 10 to 30 seconds

### **BUG FIX**

- Fixed an issue where the account status of account 2 would be displayed incorrectly on GDMS if you configure two accounts simultaneously on GDMS
- Removed “Cal History Outgoing Call” option for the “Bypass Dial Plan” setting since call history isn’t supported on LCD yet
- Fixed an issue where the phone wouldn’t download wallpapers when using HTTPS

## **FIRMWARE VERSION 1.0.1.23**

### **PRODUCT NAME**

GHP630, GHP630W, GHP631, GHP631W

### **DATE**

04/17/2024

### **FIRMWARE FILE INFORMATION**

- Firmware file name: ghp630fw.bin  
MD5: c3301c1726bba1034e6b64ca52097c07

### **ENHANCEMENT**

- Phone now disables web access while in-call to help improve performance

## **FIRMWARE VERSION 1.0.1.13**

### **PRODUCT NAME**

GHP630, GHP630W, GHP631, GHP631W

### **DATE**

03/20/2024

### **FIRMWARE FILE INFORMATION**

- Firmware file name: ghp630fw.bin  
MD5: 257f3a5e5b2bb7d9dbaeacd3f4ec3a8b

This is the Initial firmware for GHP630/630W/631/631W.