

## GXV3480/3470/3450 Firmware Release Notes

### IMPORTANT UPGRADING NOTE

- After upgrading GXV3480/3450/3470 to firmware 1.0.1.16, downgrading to a lower firmware version is not allowed.

## Table of Content

<b>IMPORTANT UPGRADING NOTE .....</b>	<b>1</b>
<b>FIRMWARE VERSION 1.0.1.21 .....</b>	<b>3</b>
PRODUCT NAME .....	3
DATE .....	3
FIRMWARE FILE INFORMATION .....	3
CHANGES SINCE FIRMWARE VERSION 1.0.1.16 .....	3
<i>ENHANCEMENT</i> .....	3
<i>BUG FIX</i> .....	3
NEW FEATURES OVERVIEW.....	4
<i>ZOOM MODE</i> .....	4
<b>FIRMWARE VERSION 1.0.1.16 .....</b>	<b>5</b>
PRODUCT NAME .....	5
DATE .....	5
FIRMWARE FILE INFORMATION .....	5
CHANGES SINCE FIRMWARE VERSION 1.0.1.9 .....	5
<i>ENHANCEMENT</i> .....	5
<i>BUG FIX</i> .....	5
NEW FEATURES OVERVIEW.....	6

## FIRMWARE VERSION 1.0.1.21

### PRODUCT NAME

GXV3480, GXV3450, GXV3470

### DATE

03/08/2023

### FIRMWARE FILE INFORMATION

- GXV3480 firmware file name: g xv3480fw.bin  
MD5: 245d1848006a686776e2a53163c784d4
- GXV3450 firmware file name: g xv3450fw.bin  
MD5: ab4c2f178c12bcdadf101354e6020718
- GXV3470 firmware file name: g xv3470fw.bin  
MD5: 146d2a157f0f2183de2539573a0fad60

### CHANGES SINCE FIRMWARE VERSION 1.0.1.16

#### ENHANCEMENT

- Supported Zoom Mode. [ZOOM MODE]


#### BUG FIX

- Fixed device media channel change from disconnecting HDMI cable to speaker does not take effect.
- Fixed device menu button display issue in a conference call after a rejection by an invitation.
- Fixed device crash issue when frequently answering a call.
- Fixed some web UI default settings issues after reset.
- Fixed device video call gets dropped automatically.
- Fixed device fails to retrieve Cust GUI file from GDMS cloud.

## NEW FEATURES OVERVIEW

### ZOOM MODE

The Zoom Mode is added to the web UI to integrate the device to Zoom app to the fullest. Switch to Zoom Mode from top right of web UI like below. The device will automatically start Zoom app. When enabled, only Zoom app runs on the phone.



## FIRMWARE VERSION 1.0.1.16

### PRODUCT NAME

GXV3480/3450/3470

### DATE

12/22/2022

### FIRMWARE FILE INFORMATION

- GXV3480 firmware file name: gxv3480fw.bin  
MD5: 245d1848006a686776e2a53163c784d4
- GXV3450 firmware file name: gxv3450fw.bin  
MD5: c46f0e8d8a4305c3caec3e2167949811
- GXV3470 firmware file name: gxv3470fw.bin  
MD5: 9741e73e4537e773db7b549586f04ba1

### CHANGES SINCE FIRMWARE VERSION 1.0.1.9

#### ENHANCEMENT

- Updated settings layout in web UI account settings.
- Added Save & Apply button for account settings.

#### BUG FIX

- Fixed device fails to send RFC2833 DTMF to all conference members.
- Fixed device displays incorrect information after being transferred by a contact.
- Fixed device displays incorrect information when adding LDAP contacts to a conference.
- Fixed device fails to retrieve custom GUI files uploaded to GDMS cloud.
- Fixed Contact app crash issue when selecting “Edit before Calling”.
- Fixed missed call prompt does not disappear on clicking when there are multiple missed calls.
- Fixed device requests audio stream from RTSP link under Baudisch mode.
- Fixed some streaming issue for multicasting.
- Fixed some issue in Peripherals settings.
- Fixed device fails to detect USB after disabling PoE power restriction.
- Fixed Presentation app audio playing issue.

- Fixed device automatically ends the call when recording file size exceeds the limit.
- Fixed device does not send INVITE when attempt to retrieve a private-held call.
- Fixed device Backup app issues such as failure to restore Google Play from backup file, automatic back cannot be disabled.
- Fixed LCD display issue when RJ9 headset is connected.

## **NEW FEATURES OVERVIEW**

(None).