

HT801 V2/HT802 V2/HT812 V2/HT814 V2/HT818 V2

Firmware Release Notes

IMPORTANT UPGRADING NOTE

Table of Content

IMPORTANT UPGRADING NOTE.....	1
HT80X V2 FIRMWARE VERSION 1.0.1.16.....	3
PRODUCT NAME.....	3
DATE.....	3
FIRMWARE FILE INFORMATION.....	3
HT81X V2 FIRMWARE VERSION 1.0.1.16.....	4
PRODUCT NAME.....	4
DATE.....	4
FIRMWARE FILE INFORMATION.....	4

HT80X V2 FIRMWARE VERSION 1.0.1.16

PRODUCT NAME

HT801 V2, HT802 V2

DATE

11/01/2024

FIRMWARE FILE INFORMATION

- HT801 V2/HT802 V2 firmware file name: ht80xv2fw.bin

MD5: afb7bd83ab82f8fc75243c34b0c7597b

This is the initial firmware for HT801 V2 and HT802 V2.

HT81X V2 FIRMWARE VERSION 1.0.1.16

PRODUCT NAME

HT812 V2, HT814 V2, HT818 V2

DATE

10/23/2024

FIRMWARE FILE INFORMATION

- HT812 V2/HT814 V2/HT818 V2 firmware file name: ht81xv2fw.bin

MD5: 127c29b093fbd24ef72737c19f5010cd

This is the initial firmware for HT812 V2, HT814 V2 and HT818 V2.